

ASS. REC. BY:

REF:

LPC1

Henneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/IV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$ 24k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBG 4069R Yr Regn: 08.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia K2500 c.c. 2497

Colour:

Blue A/C: Insured / Std / NI / NA

Sp. Reading:

47329 T/Radio: Insured / Std / NI / NA

Eng/No:

KNCSJX786G F118355

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SRIm / STD A/Rim or

Tyre Size:

F: 195R15X8  
R: Jovada 155R12X8(D)

BS/DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUKI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 11 mm

L/Bal. 6 mm

L/Bal. 11 mm

D.O.A. 12/12/24

D.O.I. 26/12/2024

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

15% N/S & N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Boss not in, nothing given to me.

Date/Time, File Pass to?

Prell. Report

Days Of Repair:

Final Report

Resurvey No. of Trip:

Survey Fee:

1)

Date/Time, File Return to?

Transportable

2)

Add Fee:  : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

S - RS - SI

Fixes

Others

Report Format :

Lump Sum / I.B.I: (\$

1074L

# POON POONG MOTORS PTE LTD

BLK 176, SIN MING DRIVE, #05-15, SIN MING AUTOCARE, SINGAPORE 575721  
 Tel:(65) 6453 2235 (24 hrs), (65) 6457 8186 Fax:(65) 6452 0022

M/S: LONPAC INSURANCE

Our Ref: ODCLAIM4069R/HEN  
 Date : 23.12.2024

Dear Sir/Mdm

*Not Authorized  
 L1/By &  
 Resurvey After Rainy  
 6 days  
 Ex & Cool*

**Insured Vehicle** **GBG4069R**  
**Insured** **JD WORKS PTE LTD**  
**Accident Date** **12.12.2024**  
**Policy Number**

## Parts Replacement Estimate

No	Product	Qty	Cost	Plus	Ext Price	
1	LEFT A PILLAR	1			Ry 480.00	✓
2	WINDSCREEN	1			CM 450.00	✓
3	LEFT SIDE MIRROR	1			Sen 280.00	✓
4	FRONT LEFT CORNER PANEL	1			R 150.00	X
5	LEFT REAR MUD SHIELD	1			220.00	?
6	TRUNK BED LEFT LOCK	1			R 90.00	X
7	REAR RAIN COVER CANVAS	1	(Inland) ??		300.00	?
8	LEFT DOOR	1			R 420.00	X
9	FRONT BUMPER	1			rd/ly 250.00	✓
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						

Subtotal (Parts): **\$2640.00**  
 Cost Plus: 15% **\$396.00**  
 Total: **\$3036.00**

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Labour Charges**

No	Labour Description	Price
1	REMOVE REFIT DAMAGE PARTS	880.00
2	WINDSCREEN REMOVE AND INSTALL	125.00
3	WINDSCREEN SILICONE	50.00
4	IU STICKER	19.00
5	PAINTWORK	900.00
6		
7		

*600*  
*1200*  
*4000*  
*✓*  
*600*

Total (labour)	\$1974.00
	-----
Total (parts & labour)	\$5010.00
	=====
Add GST 9%	\$450.90
	-----
<b>Grand Total</b>	<b>\$5460.90</b>
	=====

Henry Khoo  
96356799