

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0948/2024/EQ
DATE : 27-Dec-24
WIP : 43040

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Taufikh,

8 Days + 1 Sun + 1 PH - OK - Allan Boo

20-Jan-25

OWNER'S NAME : MR TAN GEK MENG (CHEN YIMING)

ADDRESS : 50 TOH TUCK ROAD
#02-03 SIGNATURE PARK
SINGAPORE 596741

TELEPHONE : HP +65 98450516

TYPE OF CLAIM : OWN DAMAGE CLAIM

POLICY NO : 2070145666-04

VEHICLE NO : **SFT 9117 L**

MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC

MODEL YEAR : 26/10/2020

ENGINE NO : CZD C04117

CHASSIS NO : WAUZZZF31M1001383

MILEAGE : 57,891 KM

DATE IN : 24-Dec-24

ESTIMATED BY : JOHNNY BOO / ALLAN WU

ACCIDENT DATE : 23-Dec-24

PLACE OF ACCIDENT : U-TURN LANE OUTSIDE AUSTRALIAN HIGH COMMISSION
OPPOSITE GLENEAGLES HOSPITAL GOING TOWARDS
NASSIM ROAD / HOLLAND ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFT 9117 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	\$ 800.00
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$	280.00	\$ 280.00
4	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$	1,800.00	\$ 1,800.00
5	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00	\$ 1,200.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,800.00	\$ 2,500.00
SUBTOTAL LABOUR CHARGES		: \$	9,360.00	\$ 7,060.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFT 9117 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
				\$	7,060.00
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR.	\$	3,700.00	\$	1,650.00
8	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION.	S/N \$	480.00	\$	480.00
9	TO CARRY OUT CALIBRATION FOR 360 DEGREE CAMERA SYSTEM WITH VAS TOOLS.	S/N \$	800.00	\$	800.00
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$	292.00
TOTAL LABOUR CHARGES		:	\$ 14,632.00	\$	10,282.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFT 9117 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,594.00	\$	2,074.80
2	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 148.00	\$	59.04
3	FRONT BUMPER GRILLE - CENTER	1	\$ 272.00	\$	217.20
4	FRONT BUMPER GRILLE - LH / RH	2	\$ 278.00	\$	110.80
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 238.00	\$	190.00
6	FRONT BUMPER SPOILER	1	\$ 479.00	\$	382.80
7	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 192.00	\$	153.60
8	RADIATOR GRILLE	1	\$ 1,795.00	\$	1,436.00
9	RADIATOR GRILLE STRIKER PLATE	1	\$ 303.00	\$	242.40
10	FRONT BUMPER LOWER GRILLE COVER PLATE	1	\$ 65.00	\$	51.60
11	FRONT BUMPER GUIDE SECTION - LH	1	\$ 49.00	\$	38.56
12	FRONT BUMPER TOP COVER	1	\$ 154.00	\$	123.20
13	CAUTION SIGN STICKER	1	\$ 25.00	\$	19.44
14	"OIL COMPLY WITH VW STANDARD" STICKER	1	\$ 25.00	\$	19.44
15	AIR CONDITIONER STICKER	1	\$ 10.00	\$	7.52
16	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,116.00	\$	892.80
17	FRONT BUMPER FOAM FILLER PIECE	1	\$ 129.00		
18	FRONT PARKING AID SENSOR - LH	1	\$ 286.00	\$	228.80
19	FRONT PARKING AID SEAL RING	4	\$ 11.00		
20	FRONT BUMPER WIRING SET	1	\$ 804.00		
SUB TOTAL SPARE PARTS		:	\$ 8,973.00	\$	6,248.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFT 9117 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
				\$	6,248.00
21	FRONT FENDER - LH	1	\$ 1,537.00	\$	1,229.60
22	FRONT FENDER ATTACHMENT PARTS	1	\$ 74.00		
23	FRONT FENDER BRACE - LH	1	\$ 127.00	\$	101.60
24	FRONT FENDER BRACKET - LH	1	\$ 58.00	\$	46.32
25	FRONT FENDER DAMPING - LH UPPER	1	\$ 40.00		
26	FRONT WHEEL HOUSING LINER - LH	1	\$ 289.00	\$	231.20
27	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 111.00		
28	FRONT WHEEL HOUSING LINER COVER - LH	1	\$ 20.00	\$	15.68
29	FRONT WHEEL COVER - LH / RH	2	\$ 636.00	\$	508.00
30	HEADLIGHT - LH	1	\$ 6,696.00	\$	5,356.80
31	HEADLIGHT POWER MODULE	1	\$ 904.00		
32	HEADLIGHT COMPENSATING PIECE	2	\$ 100.00	\$	39.84
33	LIFT CYLINDER - LH	1	\$ 244.00	\$	195.20
34	LIFT CYLINDER HOSE	1	\$ 102.00		
35	HEADLIGHT MOUNTING - LH	1	\$ 147.00	\$	117.60
36	LOCK CARRIER	1	\$ 1,591.00	\$	1,272.80
37	RADIATOR AIR GUIDE - LH	1	\$ 50.00	\$	39.92
38	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 112.00	\$	44.64
39	READY-MIX COOLANT	6	\$ 332.00	\$	265.44
40	HORN HIGH TONE - LH	1	\$ 162.00	\$	129.60
SUB TOTAL SPARE PARTS		:	\$ 13,332.00	\$	15,842.24

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFT 9117 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
				\$	15,842.24
41	HORN BRACKET - LH	1	\$ 28.00	\$	21.68
42	FRONT WINDSCREEN WASH WATER RESERVOIR	1	\$ 269.00	\$	214.80
43	FRONT WINDSCREEN WASHER END CAP	1	\$ 26.00		
44	FRONT WINDSCREEN WASHER HOSE	1	\$ 30.00		
45	FRONT WINDSCREEN WASHER SYSTEM PUMP	1	\$ 147.00	\$	117.60
46	FRONT WINDSCREEN WASHER PUMP SEAL	1	\$ 10.00	\$	7.60
47	FRONT DOOR COVER - LH	1	\$ 318.00		
48	HEADLIGHT - RH	1	\$ 6,696.00		
49	LIFT CYLINDER - RH	1	\$ 244.00		
50	FRONT NUMBER PLATE	S/N	\$ 60.00	\$	60.00
	ADD PARTS - SUPPLEMENTARY			\$	302.08
51	SUNDRIES		\$ 800.00	\$	39.20
TOTAL SPARE PARTS			:	\$ 30,933.00	\$ 16,605.20
TOTAL LABOUR CHARGES			:	\$ 14,632.00	\$ 10,282.00
GRAND TOTAL			:	\$ 45,565.00	\$ 26,887.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0948/2024/EQ 6-Jan-25 GLORY 1 of 1 SFT 9117 L AUDI Q3 1.4 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	RHS HEADLIGHT MOUNTING	\$ 147.00	\$ 117.60
2	BONNET RELEASE ELEMENT	\$ 73.00	\$ 57.76
3	SOCKET CONNETOR	\$ 28.00	\$ 21.68
4	WINDSCREEN WASHER PUMP SEAL	\$ 71.00	\$ 56.32
5	INTAKE AIR GUIDE LOWER	\$ 61.00	\$ 48.72
GRAND TOTAL		\$ 380.00	\$ 302.08

cra ✓
dis ✓
cra ✓
nec ✓
de ✓

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT