

ASS. REC. BY: Taught

REF: CS/A1624120390/T2P3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 800 ~~400~~

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<u>1/1</u>	
N/S	O/S

Sal. or Market Value: \$115K

IDAC Accident Report _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum. Sum: _____ % 3 Val.: Yes or No

CA 1 (REV) / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFT9117L Yr Regn: 2020 10

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q3 c.c. 1395

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 57892 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W4UZZZF31M100/383

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 215/65R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.L. 27/12/24

Survey held at Premium Benou

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt + N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
04/02/25 @ 5.34pm	confirmed with Nadia final fig \$26887.20, 8 days (Red \$19057.80, 41%)

Date/Time, File Pass to? ☐ : Prell. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 8

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Rep. Format: MER-OD

Est. Sum / B.I.: 26887.20

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0948/2024/EQ
DATE : 27-Dec-24
WIP : 43040

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR TAN GEK MENG (CHEN YIMING)
ADDRESS : 50 TOH TUCK ROAD
#02-03 SIGNATURE PARK
SINGAPORE 596741

TELEPHONE : HP +65 98450516
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070145666-04
VEHICLE NO : **SFT 9117 L**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 26/10/2020
ENGINE NO : CZD C04117
CHASSIS NO : WAUZZZF31M1001383
MILEAGE : 57,891 KM
DATE IN : 24-Dec-24
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Dec-24
PLACE OF ACCIDENT : U-TURN LANE OUTSIDE AUSTRALIAN HIGH COMMISSION
OPPOSITE GLENEAGLES HOSPITAL GOING TOWARDS
NASSIM ROAD / HOLLAND ROAD



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFT 9117 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID. S/N \$	480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULE. S/N \$	800.00 ✓	
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR. S/N \$	280.00 ✓	
4	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. S/N \$	1,800.00 ✓	
5	TO CARRY OUT VACUUM AND REGAS FOR R1234. S/N \$	1,200.00 ✓	
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. \$	4,800.00 2500	
SUBTOTAL LABOUR CHARGES		: \$ 9,360.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFT 9117 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, ✓ X BONNET AND LHS FRONT DOOR. ✓	\$ 3,700.00	1650
8	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION. S/N	\$ 480.00 ✓	
9	TO CARRY OUT CALIBRATION FOR 360 DEGREE CAMERA SYSTEM WITH VAS TOOLS. S/N	\$ 800.00 ✓	
10	TO CARRY OUT DIAGNOSTIC CHECK. S/N	\$ 292.00 ✓	
TOTAL LABOUR CHARGES		: \$ 14,632.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFT 9117 L

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER	1	\$	2,594.00	de
2	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$	148.00	?
3	FRONT BUMPER GRILLE - CENTER	1	\$	272.00	cuq
4	FRONT BUMPER GRILLE - LH / RH	2	\$	278.00	RHX LHare
5	FRONT BUMPER CLOSING ELEMENT	1	\$	238.00	?
6	FRONT BUMPER SPOILER	1	\$	479.00	de
7	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$	192.00	?
8	RADIATOR GRILLE	1	\$	1,795.00	ant
9	RADIATOR GRILLE STRIKER PLATE	1	\$	303.00	?
10	FRONT BUMPER LOWER GRILLE COVER PLATE	1	\$	65.00	mis
11	FRONT BUMPER GUIDE SECTION - LH	1	\$	49.00	de
12	FRONT BUMPER TOP COVER	1	\$	154.00	de
13	CAUTION SIGN STICKER	1	\$	25.00	nei
14	"OIL COMPLY WITH VW STANDARD" STICKER	1	\$	25.00	nei
15	AIR CONDITIONER STICKER	1	\$	10.00	nei
16	FRONT BUMPER REINFORCEMENT BEAM	1	\$	1,116.00	?
17	FRONT BUMPER FOAM FILLER PIECE	1	\$	129.00	?
18	FRONT PARKING AID SENSOR - LH	1	\$	286.00	?
19	FRONT PARKING AID SEAL RING	4	\$	11.00	nei
20	FRONT BUMPER WIRING SET	1	\$	804.00	?
SUB TOTAL SPARE PARTS		:	\$	8,973.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFT 9117 L

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT FENDER - LH	1	\$	1,537.00	bt ✓
22	FRONT FENDER ATTACHMENT PARTS	1	\$	74.00	X
23	FRONT FENDER BRACE - LH	1	\$	127.00	?
24	FRONT FENDER BRACKET - LH	1	\$	58.00	?
25	FRONT FENDER DAMPING - LH UPPER	1	\$	40.00	?
26	FRONT WHEEL HOUSING LINER - LH	1	\$	289.00	fr ✓
27	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	111.00	X
28	FRONT WHEEL HOUSING LINER COVER - LH	1	\$	20.00	fr ✓
29	FRONT WHEEL COVER - LH / RH	2	\$	636.00	ent ✓
30	HEADLIGHT - LH	1	\$	6,696.00	aw ✓
31	HEADLIGHT POWER MODULE	1	\$	904.00	?
32	HEADLIGHT COMPENSATING PIECE	2	\$	100.00	rel ✓
33	LIFT CYLINDER - LH	1	\$	244.00	aw ✓
34	LIFT CYLINDER HOSE	1	\$	102.00	?
35	HEADLIGHT MOUNTING - LH	1	\$	147.00	?
36	LOCK CARRIER	1	\$	1,591.00	aw ✓
37	RADIATOR AIR GUIDE - LH	1	\$	50.00	?
38	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$	112.00	?
39	READY-MIX COOLANT	6	\$	332.00	rel ✓
40	HORN HIGH TONE - LH	1	\$	162.00	?
SUB TOTAL SPARE PARTS		:	\$	13,332.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFT 9117 L

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HORN BRACKET - LH	1	\$ 28.00	?
42	FRONT WINDSCREEN WASH WATER RESERVOIR	1	\$ 269.00	de ✓
43	FRONT WINDSCREEN WASHER END CAP	1	\$ 26.00	X
44	FRONT WINDSCREEN WASHER HOSE	1	\$ 30.00	?
45	FRONT WINDSCREEN WASHER SYSTEM PUMP	1	\$ 147.00	?
46	FRONT WINDSCREEN WASHER PUMP SEAL	1	\$ 10.00	?
47	FRONT DOOR COVER - LH	1	\$ 318.00	?
48	HEADLIGHT - RH	1	\$ 6,696.00	?
49	LIFT CYLINDER - RH	1	\$ 244.00	?
50	FRONT NUMBER PLATE	S/N	\$ 60.00	na ✓
51	SUNDRIES		\$ 800.00	?
TOTAL SPARE PARTS		:	\$ 30,933.00	
TOTAL LABOUR CHARGES		:	\$ 14,632.00	
GRAND TOTAL		:	\$ 45,565.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Taufik 97495749 / 62563561
Not Authorise Ex: to be advise
27/12/2012 430 pm
P/P Resurvey before paint.
08 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT