

## **QUOTATION**

CODE: C0011 PAGE NO.:

CUSTOMER: CHINA TAIPING INSURANCE (SINGAPO DOCUMENT NO.: 1186 ADDRESS: 3 ANSON ROAD DOCUMENT DATE: 09/04/2025

ADDRESS: 3 ANSON ROAD DOCUMENT DATE: #16-00 SPRINGLEAF TOWER POS ID:ES

SINGAPORE 079909 PRINTED BY: Manojj Baloo ATTN: MOTOR CLAIM DEPT SERVICE ADV: Manojj Baloo CSP/OP CODE: Manojj Baloo

CONTACT NO.: 2222366 DEPT: W

MODEL: 911 Turbo S Coupe WIP NO.: 32506

CHASSIS NO.: WP0ZZZ99ZFS161645 REF. NO.: DS/SNV163G/0371 ENGINE NO.: SF05533 DATE IN: 03/02/2025

ENGINE NO.: SF05533 DATE IN: REG NO.: SNV163G EXT. WTY:

REGN DATE: MILEAGE: 41,021

DESCRIPTION: Body & Upholstery

Item	Description	Qty. Unit Price Stk/S		Gross GST amount Code	
			SGD	SGD	
NOTES	ACCIDENT REPAIR - TP CLAIM - CHINA TAIPING INS	0.00	0.00	0.00	0
INS-PB-(L)	TO REMOVE / REPLACE REAR BUMPER, REINFORCEMENT & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR REAR END PANEL & ALL AREAS AFFECTED BY THE ACCIDENT.	3,440.00	1.00	3,440.00	S
INS-PAINT-(L)	TO RESPRAY REAR BUMPER,REAR BUMPER LOWER SPOILER,REAR END PANEL.	2,800.00	1.00	2,800.00	S
INS-PB-(L)	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	1,720.00	1.00	1,720.00	S
INS-PB-(L)	TO TRANSFER THE REAR BUMPER SENSORS.	250.00	1.00	250.00	S
INS-PB-(L)	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.00	1.00	150.00	S
INS-PB-(L)	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	600.00	1.00	600.00	S
INS-PB-(L)	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	300.00	1.00	300.00	S
INS-PB-(L)	SUNDRIES.	20.00	1.00	20.00	S
991-505-652-01-1E	0 EXHAUST TRIM RH	1.00	449.00	314.30	S
991-505-666-00-1E	0 GRILLE FRAME RH	1.00	303.40	212.38	S
991-505-864-00-1E	0 DISC FOR FRAME GRILLE RH	1.00	173.00	121.10	S
991-505-837-00-	RETAINING STRIP LOWER	1.00	78.10	54.67	S
991-505-141-02-	BUMPER REINFORCEMENT	1.00	1,495.40	1,046.78	S
991-559-235-00-	LOGO PORSCHE CHROMED	1.00	266.40	186.48	S

Co. Regn. No. 198602110Z

GST Regn. No. M90364005A

1

<sup>\*</sup>This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

<sup>\*</sup>Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

<sup>\*</sup>This estimate is valid for a period of thirty (30) days only.

<sup>\*</sup>Prices are subject to change without prior notice.



## **QUOTATION**

CODE: C0011
CUSTOMER: CHINA TAIPING INSURANCE (SINGAPO

ADDRESS: 3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

ATTN: MOTOR CLAIM DEPT

CONTACT NO.: 2222366

MODEL: 911 Turbo S Coupe CHASSIS NO.: WP0ZZZ99ZFS161645

ENGINE NO.: SF05533

REG NO.: SNV163G REGN DATE:

DESCRIPTION: Body & Upholstery

PAGE NO.: 2 DOCUMENT NO.: 1186

DOCUMENT DATE: 09/04/2025

POS ID: ES

PRINTED BY: Manojj Baloo SERVICE ADV: Manojj Baloo CSP/OP CODE: Manojj Baloo

DEPT: W WIP NO.: 32506

REF. NO.: DS/SNV163G/0371

DATE IN: 03/02/2025

EXT. WTY:

MILEAGE: 41,021

Item	Description	Qty.	Unit Price Stk/Status	Gross amount SGD	
991-559-231-02-	LOGO "911" SMALL	1.00	181.30	126.91	S
991-559-247-00-	LOGO "TURBO"	1.00	533.80	373.66	S
991-559-243-01-	LOGO S CHROMED	1.00	132.80	92.96	S
991-631-144-16-	TAIL LIGHT RH	1.00	1,900.50	1,330.35	S
991-631-496-02-	REFELCTOR RH	1.00	103.00	72.10	S
991-111-762-62-	TAIL PIPE RH	1.00	3,687.40	2,581.18	S
997-111-107-31-	GASKET FOR EXHAUST MANIFOLD RH	1.00	59.30	41.51	Š
991-111-731-71-	EXHAUST SILENCER	1.00	3,339.50	2,337.65	Š
997-111-230-81-	CLAMP	2.00	111.10	155.54	Š
997-111-240-30-	Clip	2.00	84.30	118.02	S
991-504-510-05-	REAR FENDER UNDERSHILED RH SMALL	1.00	518.40	362.88	S
	E0 Air guide Black	1.00	1,084.11 de√	758.88	S
991-110-640-73-	Charge air cooler	1.00	3,211.18 bt 🗸	2,247.83	S
991-110-626-71-	Pressure line	1.00	663.06dis <b>√</b>	464.15	S
991-504-254-00-	Bracket	1.00	1,588.82 bt ✓	1,112.18	S
991-505-921-10-	REAR BUMPER	1.00	2,722.90	1,906.03	S
991-505-975-02-0	S2XREAR BUMPER LOWER SPOILER	1.00	1,720.90	1,204.63	S
991-505-480-01-	Heat protection	1.00	485.40	339.78	S
PAF-008-434	Washer for rubber mount	2.00	3.88 nec	5.44	S
900-116-007-02-	Lock	2.00	8.00 nec	11.20	S

<sup>\*</sup>This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

<sup>\*</sup>Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

<sup>\*</sup>This estimate is valid for a period of thirty (30) days only.

<sup>\*</sup>Prices are subject to change without prior notice.



## **QUOTATION**

CODE: C0011

CUSTOMER: CHINA TAIPING INSURANCE (SINGAPO

ADDRESS: 3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

ATTN: MOTOR CLAIM DEPT

CONTACT NO.: 2222366

MODEL: 911 Turbo S Coupe CHASSIS NO.: WP0ZZZ99ZFS161645

ENGINE NO.: SF05533

REG NO.: SNV163G REGN DATE:

DESCRIPTION: Body & Upholstery

PAGE NO.: 3 DOCUMENT NO.: 1186

DOCUMENT DATE: 09/04/2025

POS ID: ES

PRINTED BY: Manojj Baloo SERVICE ADV: Manojj Baloo CSP/OP CODE: Manojj Baloo

DEPT: W

WIP NO.: 32506

REF. NO.: DS/SNV163G/0371

DATE IN: 03/02/2025

EXT. WTY:

MILEAGE: 41,021

Item	Description	Qty. Unit Price Stk/Status	Qty. Unit Price Stk/Status Gross G	
		SGD	SGD	
999-703-267-40- 999-702-319-41-	Bush Grommet	2.00 5.18 nec 2.00 19.29 nec 7	7.26 27.01	S S

	*	GST Code	Rate	Service/Goods	GST		Before GS
Parts	17,612.86	0	-		-	Gross *	26,892.86
Surcharge	0.00	S	9.00%	26,892.86	2,420.36	Less: Deposit **	0.00
Labour	9,280.00					Amount Due	26,892.86
Menus	0.00						-

	Before GST	GST	Total
Gross *	26,892.86	2,420.36	29,313.22
Less: Deposit **	0.00	0.00	0.00
Amount Due	26,892.86	2,420.36	29,313.22

<sup>\*</sup>This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*\* Deposit tax invoice No.:

		Eurokars Services Pte Ltd
	<u> </u>	
	Customer signature	Authorised signature
Date:		

Eurokars Aftersales Centre
Co. Regn. No. 198602110Z 27A Tanjong Penjuru, Level 5
GST Regn. No. M90364005A Singapore 609042

Tel: (65) 6331 0680 Fax: (65) 6331 0690

Website: www.eurokarsservices.com.sg

Page 2 of 2

<sup>\*</sup>Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

<sup>\*</sup>This estimate is valid for a period of thirty (30) days only.

<sup>\*</sup>Prices are subject to change without prior notice.