

QUOTATION

CODE: C0011
CUSTOMER: CHINA TAIPING INSURANCE (SINGAPO)
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
ATTN: MOTOR CLAIM DEPT

CONTACT NO.: 2222366
MODEL: 911 Turbo S Coupe
CHASSIS NO.: WP0ZZZ99ZFS161645
ENGINE NO.: SF05533
REG NO.: SNV163G
REGN DATE:

PAGE NO.: 1
DOCUMENT NO.: 812
DOCUMENT DATE: 23/12/2024
POS ID: ES
PRINTED BY: Eric Paul
SERVICE ADV:
CSP/OP CODE: Eric Paul
DEPT: W
WIP NO.: 32506
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	TP CLAIM - CHINA TAIPING	1720	0.00		0.00	O
INS-PB-(L)	TO REMOVE /REPLACE REAR BUMPER, REINFORCEMENT & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR REAR END PANEL & ALL AREAS AFFECTED BY THE ACCIDENT.	5,160.00	1.00	13440	5,160.00	S
INS-PAINT-(L)	TO RESPRAY REAR BUMPER, REAR BUMPER LOWER SPOILER, REAR END PANEL. ?	4,200.00	1.00	12800	4,200.00	S
INS-PB-(L)	TO CARRY-OUT BODY CAVITY PRESERVATION.	250.00	1.00	nnx	250.00	S
INS-PB-(L)	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	1,720.00	1.00	ptsp. 2x	1,720.00	S
INS-PB-(L)	TO TRANSFER THE REAR BUMPER SENSORS.	500.00	1.00	250	500.00	S
INS-PB-(L)	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	250.00	1.00	150	250.00	S
INS-PB-(L)	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	600.00	1.00		600.00	S
INS-PB-(L)	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	300.00	1.00	janie 2	300.00	S
INS-PB-(L)	SUNDRIES.	50.00	1.00	20	50.00	S
991-505-921-02-	REAR BUMPER	1.00	2,722.90	de	2,722.90	S
991-505-803-01-G2X	TOWING COVER	1.00	30.90	nnx	30.90	S
991-505-975-00-G2X	REAR BUMPER LOWER SPOILER	1.00	1,618.10	de	1,618.10	S
991-505-651-01-1E0	EXHAUST TRIM LH	1.00	449.00	nnx	449.00	S
991-505-652-01-1E0	EXHAUST TRIM RH	1.00	449.00	dis	449.00	S

Tanjik 97495749 / 62563561
wp 26/12/24 @ 2:15pm 7 days
P/P Resurvey before paint. 5 days
Tanjik @ khauto.com.

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

*This estimate is valid for a period of thirty (30) days only.

*Prices are subject to change without prior notice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

date:

QUOTATION

CODE: C0011
CUSTOMER: CHINA TAIPING INSURANCE (SINGAPO)
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
ATTN: MOTOR CLAIM DEPT

PAGE NO.: 2
DOCUMENT NO.: 812
DOCUMENT DATE: 23/12/2024
POS ID: ES
PRINTED BY: Eric Paul
SERVICE ADV: Eric Paul
CSP/OP CODE: W
DEPT: 32506
WIP NO.:
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

CONTACT NO.: 2222366
MODEL: 911 Turbo S Coupe
CHASSIS NO.: WP0ZZZ99ZFS161645
ENGINE NO.: SF05533
REG NO.: SNV163G
REGN DATE:

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
991-505-666-00-1E0	GRILLE FRAME RH	1.00	303.40		mis/ 303.40	S
991-505-864-00-1E0	DISC FOR FRAME GRILLE RH	1.00	173.00		mis/ 173.00	S
991-505-837-00-	RETAINING STRIP LOWER	1.00	78.10		de/ 78.10	S
991-505-836-02-	TAIL LIGHT BRACKET RH	1.00	382.60		nn/ 382.60	S
5Q0-919-275-B-G2X	BUMPER SENSOR	2.00	319.80		nn/ 639.60	S
5Q0-919-133- -9B9	SENSOR GASKET	4.00	3.90		nel/ 15.60	S
991-505-636-00-	BUMPER RETAINER RH	1.00	261.90		nn/ 261.90	S
PAF-008-543- -	BUMPER CLIPS	8.00	2.80		nn/ 22.40	S
999-190-191-30-	BLIND RIVET	8.00	8.10		nn/ 64.80	S
991-505-480-01-	HEAT SHIELD RH → heat protection	1.00	485.40	✓	bt/ 485.40	S
991-505-481-00-	HEAT SHIELD LOWER RH	1.00	303.60		nn/ 303.60	S
991-505-471-00-	HEATSHIELD CENTER UPPER	1.00	379.80		nn/ 379.80	S
991-505-141-02-	BUMPER REINFORCEMENT	1.00	1,495.40		bt/ 1,495.40	S
991-559-235-00-	LOGO PORSCHE CHROMED	1.00	266.40		nel/ 266.40	S
991-559-231-02-	LOGO "911" SMALL	1.00	181.30		nel/ 181.30	S
991-559-247-00-	LOGO "TURBO"	1.00	533.80		nn/ 533.80	S
991-559-243-01-	LOGO S CHROMED	1.00	132.80		nel/ 132.80	S
991-631-144-16-	TAIL LIGHT RH	1.00	1,900.50		cut/ 1,900.50	S
991-631-496-02-	REFLECTOR RH	1.00	103.00		mis/ 103.00	S
991-111-762-62-	TAIL PIPE RH	1.00	3,687.40		bt/ 3,687.40	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

*This estimate is valid for a period of thirty (30) days only.

*Prices are subject to change without prior notice.

QUOTATION

CODE: C0011
 CUSTOMER: CHINA TAIPING INSURANCE (SINGAPO
 ADDRESS: 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909
 ATTN: MOTOR CLAIM DEPT

CONTACT NO.: 2222366
 MODEL: 911 Turbo S Coupe
 CHASSIS NO.: WP0ZZZ99ZFS161645
 ENGINE NO.: SF05533
 REG NO.: SNV163G
 REGN DATE:

PAGE NO.: 3
 DOCUMENT NO.: 812
 DOCUMENT DATE: 23/12/2024
 POS ID: ES
 PRINTED BY: Eric Paul
 SERVICE ADV: Eric Paul
 CSP/OP CODE: W
 DEPT: 32506
 WIP NO.:
 REF. NO.:
 DATE IN:
 EXT. WTY:
 MILEAGE: 0

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
991-111-712-71-	EXHAUST MANIFOLD RH	1.00	1,803.70		1,803.70	S
997-111-107-31-	GASKET FOR EXHAUST MANIFOLD RH	1.00	59.30		59.30	S
997-113-010-AX-	CATALYTIC CONVERTER	1.00	8,452.60		8,452.60	S
9A1-606-188-01-	Oxygen sensor	1.00	575.70		575.70	S
991-111-731-71-	EXHAUST SILENCER	1.00	3,339.50		3,339.50	S
997-111-230-81-	CLAMP	2.00	111.10		222.20	S
991-111-371-70-	RESTRAINING STRAP	2.00	181.60		363.20	S
991-111-473-01-	SUPPORT BRACKET FOR EXHAUST	1.00	284.50		284.50	S
997-111-240-30-	Clip	2.00	84.30		168.60	S
997-111-215-70-	SILENCER GASKET	2.00	44.10		88.20	S
991-504-306-02-	REAR FENDER UNDERSHIELD RH BIG	1.00	565.00		565.00	S
991-504-510-05-	REAR FENDER UNDERSHIELD RH SMALL	1.00	518.40		518.40	S

		* GST Code	Rate	Service/Goods	GST		Before GST	GST	Total
Parts	33,121.60	O	-		-	Gross	46,151.60	4,153.64	50,305.24
Surcharge	0.00	S	9.00%	46,151.60	4,153.64	Less: Deposit **	0.00	0.00	0.00
Labour	13,030.00					Amount Due	46,151.60	4,153.64	50,305.24
Menus	0.00								

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of S180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

** Deposit tax invoice No.:

*This estimate is valid for a period of thirty (30) days only.

*Prices are subject to change without prior notice.

Eurokars Services Pte Ltd

Date: _____

Customer signature

Authorised signature