

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

TP M 816.

VERON.

VEHICLE NO : SNP 2499 G

MAKE / MODEL : SUBARU WRX

CHASSIS NO : JF1VBHK85PG007011

ACCIDENT DATE : 11.12.2024

NO	DESCRIPTION	QTY	AMOUNT (\$)
LIST ITEMS			
1	Front bumper <i>Delnd</i>	1	\$ 854.16 ✓
2	Front bumper RH hold <i>del</i>	1	\$ 78.00 ✓
3	Front bumper RH side garnish <i>cut</i>	1	\$ 46.44 ✓
4	Front bumper lower side garnish <i>the w</i>	1	\$ 86.04 ✓
5	Front bumper clips <i>aler</i>	1	\$ 72.00 ✓
6	Front RH head lamp <i>cut</i>	1	\$ 3614.28 ✓
			\$ 4750.92
			LESS 20% DISC \$ 950.184
			TOTAL \$ 3800.74

466488
3731.90

LABOUR COST			
1	Remove, replace + repair consistent to the accident	1	\$ 1000.00 <i>250</i>
2	Respray painting	1	\$ 800.00 <i>20</i>
TOTAL			\$ 1800.00
GRAND TOTAL			\$ 5600.74 <i>450</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adm G
2/s 30/12/24.
D3Dgn

total: 4181.90

2/s : 3314 ✓