

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

SUPPLEMENTARY

ESTIMATE

EST. No EST0036430
United Overseas Insurance Ltd
146 Robinson Road
#02-01 UOI Building
Singapore 068909

Page 1 of 1
Your ref. DHOM110182242202
Job No. 74899
Our ref. 24.12.17
Payment
Date 23/1/2025

Attn

Vehicle No ... : YQ 3043X
Vehicle Model : Mitsubishi Canter
Accident on ... : 16/12/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
SUPPLEMENTARY ITEMS:					
1.00	Pc	Front door glass channel LH	135.00	dd	135.00 ✓
1.00	Pc	Front side panel rubber seal	28.00	nec	28.00 ✓
1.00	Pc	Fuel injector	390.00	nc	390.00 x
Total amount of parts supplied-S\$553.00					
1.00		10% of parts supplied:	55.30		55.30

Sub-Total 608.30
GST 9.00% 54.75
Total S\$ 663.05

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0036430
United Overseas Insurance Ltd
146 Robinson Road
#02-01 UOI Building
Singapore 068909

Page 1 of 3
Your ref. DHOM110182242202
Job No. 74899
Our ref. 24.12.17
Payment
Date 24/12/2024

Attn/.....

Vehicle No YQ 3043X
Vehicle Model : Mitsubishi Canter
Accident on ... 16/12/2024

Not Authorized
Running B4 pain
ex B600
9 days

before
before
before
13.01.25
by me

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front windscreen	550.00		CM ✓ 550.00 ✓
1.00	Pc	Front windscreen rubber	220.00		CM ✓ 220.00 ✓
1.00	Pc	Front door LH (OEM)	480.00		CM ✓ 480.00 ✓
1.00	Pc	Front door lower garnish LH	60.00		CM ✓ 60.00 ✓
1.00	Pc	Front door outer handle LH	65.00	55	CM ✓ 65.00 ✓
1.00	Pc	Front door mirror LH (big)	25.00		CM ✓ 25.00 ✓
1.00	Pc	Front door mirror LH (small)	50.00	40	CM ✓ 50.00 ✓
1.00	Pc	Front signal lamp LH	180.00	175	CM ✓ 180.00 ✓
1.00	Pc	Front headlamp side cover LH	125.00		CM ✓ 125.00 ✓
1.00	Pc	BLUETEC sticker LH	40.00		CM ✓ 40.00 ✓
1.00	Pc	Warning decal	40.00		nec SN ✓ 40.00 ✓
1.00	Pc	Rear bumper side LH	100.00		SVC ✓ 100.00 X
1.00	Pc	Rear carriage drop door stopper LH	5.00		SVC ✓ 5.00 X
1.00	Pc	Step garnish LH (outer)	350.00		mtg cra ✓ 350.00 ✓
3 2.00	Pcs	Fuel injectors	390.00		SVC 1170 780.00 X
1.00	Pc	Fuel injector line	155.00		SVC ✓ 155.00 X
Total amount of parts supplied-S\$3,225.00					3445

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明 記) 摩 哆 有 限 公 司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0036430
United Overseas Insurance Ltd
146 Robinson Road
#02-01 UOI Building
Singapore 068909

Page: 2 of 3
Your ref.: DHOM110182242202
Job No.: 74899
Our ref: 24.12.17
Payment:
Date: 24/12/2024

Attn

Vehicle No: YQ 3043X
Vehicle Model : Mitsubishi Canter
Accident on ...: 16/12/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		10% of parts supplied:	322.50	344.50	322.50
		Special nett item:			
1.00	Pc	Rear carriage drop door c/w board LH	800.00		<i>B₂</i> 800.00 ✓
1.00	Pc	Rear carriage drop door c/w board RH	800.00		<i>B₂</i> 800.00 ✓
1.00	Pc	Rear carriage drop door rail LH	650.00		<i>B1/D1</i> 650.00 ✓
1.00	Pc	Rear carriage drop door rail RH	650.00		<i>B₂</i> 650.00 ✓
1.00	Pc	Rear carriage drop door handle LH (front)	40.00		<i>D1</i> 40.00 ✓
1.00	Pc	IU bracket	15.00		<i>M₂</i> 15.00 ✓
1.00	Litre	Engine oil (XHP ESP) <i>necessary</i>	16.00		nec 16.00 ✓
		Labour & Misc:			3011
1.00		Towing fee	60.00		60.00 ✓
1.00		To dismantle+renew front windscreen	180.00		180.00 <i>1201</i>
1.00		To remove+refix/renew fuel injectors+fuel	200.00		200.00 <i>1601</i>

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0036430
United Overseas Insurance Ltd
146 Robinson Road
#02-01 UOI Building
Singapore 068909

Page: 3 of 3
Your ref.: DHOM110182242202
Job No.: 74899
Our ref.: 24.12.17
Payment
Date: 24/12/2024

Attn

Vehicle No: YQ 3043X
Vehicle Model : Mitsubishi Canter
Accident on ...: 16/12/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		injector line, to remove engine oil (accumulated above pistons), etc			
1.00		To knock dents on front windscreen pillar LH, 'B' pillar LH, cabin roof side panel LH and renew parts	900.00		900.00
1.00		To spray paint	1,200.00		1,200.00
					<u>2240</u>

Sub-Total 9,058.50
GST 9.00% 815.27
Total S\$ 9,873.77

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."