

REF:

ASSIGNMENT

From _____ Date: _____
 Estn ^{Estimate} _____
 OD / ~~TP~~ / TP RES / CD RES / EVA / INV / MV
 To in _____ Vehicle No: _____
 at _____
 of _____
 Insured: _____
 Policy No _____
 Claim No _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Vch _____
 (Policy Condition)

Veh No: SDW68L Yr Regn: 2019 Sept
 Type: M. Car / M. Cycle / Bus / Van / Lorr. / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Audi A5 Sportback 1984
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 84217 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZZF50KA 078955
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: OK / Jammed / Leaked / Burnt or _____
 Brake: OK / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 245/40 R18
 R: 245/40 R18

Remark: Vehicle had commenced its repair at the time of inspection.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

BS / DUN / EXNOVA / GY / FS / I / IZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Bal. or Market Value: _____
 IDAC Accident Report _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 27/12/24
 Survey held at Premium
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP AI6 AI6.
	COE Expiry
	Estimate given during: Yes () 1st Survey: No ()
	MV:
	PV:
	Nett:

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Format: _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Addl Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Inve (\$) _____
 Survey Fee: _____
 Transportation: _____
 3 + RS. \$1 _____
 Photos _____
 Others _____



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0946/2024/EQ
DATE : 26-Dec-24
WIP : 43139

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/12/2024
YOUR INSURED VEH NO : EF 45 E

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

OWNER'S NAME : MS GOH KAH GIN
ADDRESS : 35 AMBER GARDENS
#11-11 THE ESTA
SINGAPORE 439966
TELEPHONE : HP +65 97777977
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : DMPPHQ24-010327
VEHICLE NO : **SDW 68 L**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 30/9/2019
ENGINE NO : CVK 088017
CHASSIS NO : WAUZZZF50KA078955
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Dec-24
PLACE OF ACCIDENT : TOMLINSON ROAD TRAFFIC JUNCTION TURN TO TANGLIN ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDW 68 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	400.00 250	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00 1000	
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00 1100	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00 ✓	
TOTAL LABOUR CHARGES		:	\$	5,572.00



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDW 68 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Defend</i>	1	\$ 2,802.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 458.00	x
3	FRONT BUMPER SECURING STRIP <i>new</i>	1	\$ 45.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 286.00	+
5	FRONT BUMPER AIR GUIDE - LH	1	\$ 71.00	x
6	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 598.00	✓
7	FRONT BUMPER GUIDE SECTION - LH	1	\$ 46.00	x
8	FRONT BUMPER TOP BRACKET	1	\$ 173.00	x
9	FRONT PARKING AID SENSOR - LH OUTER	1	\$ 286.00	x
10	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 11.00	x
11	HEADLIGHT - LH <i>cut</i>	1	\$ 9,447.00	✓
12	HEADLIGHT COMPENSATING PIECE <i>new</i>	2	\$ 100.00	x
13	LIFT CYLINDER - LH <i>new</i>	1	\$ 238.00	x
14	LIFT CYLINDER BRACKET - LH <i>new</i>	1	\$ 19.00	x
15	LIFT CYLINDER HOSE <i>new</i>	1	\$ 110.00	x
16	FRONT FENDER - LH <i>Dented</i>	1	\$ 1,264.00	✓
17	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 62.00	x
18	FRONT FENDER CLOSING ELEMENT - LH ?	1	\$ 92.00	?
19	FRONT FENDER BRACKET - LH FRONT ?	1	\$ 45.00	?
20	FRONT FENDER RIVET <i>new</i>	6	\$ 26.00	✓
SUB TOTAL SPARE PARTS			\$ 16,179.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDW 68 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET - LH REAR <i>NEW</i>	1	\$ 73.00	+
22	FRONT FENDER BRACKET - LH CENTER <i>NEW</i>	1	\$ 56.00	+
23	FRONT FENDER BRACE - LH ?	1	\$ 177.00	?
24	FRONT FENDER LOWER BRACKET - LH <i>NEW</i>	1	\$ 61.00	+
25	FRONT FENDER CHROME TRIM - LH <i>NEW</i>	1	\$ 192.00	-
26	FRONT FENDER LEDGE COVER - LH INNER	1	\$ 64.00	+
27	FRONT FENDER LEDGE COVER - LH OUTER LONG	1	\$ 45.00	+
28	FRONT FENDER LEDGE COVER - LH OUTER SHORT	1	\$ 20.00	+
29	FRONT WHEEL HOUSING LINER - LH <i>NEW</i>	1	\$ 332.00	+
30	FRONT WHEEL SPOILER <i>NEW</i>	1	\$ 92.00	+
31	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>NEW</i>	1	\$ 190.00	+
32	SIDE MEMBER TRIM ATTACHMENT PARTS ?	1	\$ 153.00	+
33	SIDE MEMBER TRIM ADHESIVE TAPES	1	\$ 233.00	+
34	FRONT ALUMINIUM RIM - LH	1	\$ 2,123.00	+
35	FRONT ALUMINIUM RIM RUBBER VALVE - LH	1	\$ 5.00	+
36	SUNDRIES ?		\$ 500.00	?
TOTAL SPARE PARTS			\$ 20,495.00	
TOTAL LABOUR CHARGES			\$ 5,572.00	
GRAND TOTAL			\$ 26,067.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adam Lim*
SURVEYED DATE : *27/12/24.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT