



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0946/2024/EQ
DATE : 26-Dec-24
WIP : 43139

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/12/2024

YOUR INSURED VEH NO : EF 45 E

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS GOH KAH GIN
ADDRESS : 35 AMBER GARDENS
#11-11 THE ESTA
SINGAPORE 439966
TELEPHONE : HP +65 97777977
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : DMPPHQ24-010327
VEHICLE NO : **SDW 68 L**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 30/9/2019
ENGINE NO : CVK 088017
CHASSIS NO : WAUZZZF50KA078955
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Dec-24
PLACE OF ACCIDENT : TOMLINSON ROAD TRAFFIC JUNCTION TURN TO TANGLIN ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDW 68 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,000.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00	
TOTAL LABOUR CHARGES		: \$ <u>5,572.00</u>	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDW 68 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,802.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 458.00	
3	FRONT BUMPER SECURING STRIP	1	\$ 45.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 286.00	
5	FRONT BUMPER AIR GUIDE - LH	1	\$ 71.00	
6	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 598.00	
7	FRONT BUMPER GUIDE SECTION - LH	1	\$ 46.00	
8	FRONT BUMPER TOP BRACKET	1	\$ 173.00	
9	FRONT PARKING AID SENSOR - LH OUTER	1	\$ 286.00	
10	FRONT PARKING AID SEAL RING	4	\$ 11.00	
11	HEADLIGHT - LH	1	\$ 9,447.00	
12	HEADLIGHT COMPENSATING PIECE	2	\$ 100.00	
13	LIFT CYLINDER - LH	1	\$ 238.00	
14	LIFT CYLINDER BRACKET - LH	1	\$ 19.00	
15	LIFT CYLINDER HOSE	1	\$ 110.00	
16	FRONT FENDER - LH	1	\$ 1,264.00	
17	FRONT FENDER ATTACHMENT PARTS	1	\$ 62.00	
18	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 92.00	
19	FRONT FENDER BRACKET - LH FRONT	1	\$ 45.00	
20	FRONT FENDER RIVET	6	\$ 26.00	
SUB TOTAL SPARE PARTS			\$ 16,179.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDW 68 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET - LH REAR	1	\$ 73.00	
22	FRONT FENDER BRACKET - LH CENTER	1	\$ 56.00	
23	FRONT FENDER BRACE - LH	1	\$ 177.00	
24	FRONT FENDER LOWER BRACKET - LH	1	\$ 61.00	
25	FRONT FENDER CHROME TRIM - LH	1	\$ 192.00	
26	FRONT FENDER LEDGE COVER - LH INNER	1	\$ 64.00	
27	FRONT FENDER LEDGE COVER - LH OUTER LONG	1	\$ 45.00	
28	FRONT FENDER LEDGE COVER - LH OUTER SHORT	1	\$ 20.00	
29	FRONT WHEEL HOUSING LINER - LH	1	\$ 332.00	
30	FRONT WHEEL SPOILER	1	\$ 92.00	
31	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 190.00	
32	SIDE MEMBER TRIM ATTACHMENT PARTS	1	\$ 153.00	
33	SIDE MEMBER TRIM ADHESIVE TAPES	1	\$ 233.00	
34	FRONT ALUMINIUM RIM - LH	1	\$ 2,123.00	
35	FRONT ALUMINIUM RIM RUBBER VALVE - LH	1	\$ 5.00	
36	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS			\$ 20,495.00	
TOTAL LABOUR CHARGES			\$ 5,572.00	
GRAND TOTAL			\$ 26,067.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT