



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2505135

INV Date 05/08/2025

Reference CD/LPC24120398/Kpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMS 9912E
Insured Veh. YP 9840C
Claim No. 24/24/25/VC05/030368
Policy No. Z24VC05000859
Accident Date 23/12/2024
Inspection Date 26/12/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CD/LPC24120398/Kpa3q2(N)	
			Date: 05/08/2025	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 9840C	Veh. Inspected	SMS 9912E
	Policy No.	Z24VC05000859	Coverage (\$)	0.00
	Claim No.	24/24/25/VC05/030368	Excess (\$)	0.00
	Assign From	CHARMAINE KONG	Assign Date	26/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI AVANTE (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	KMHD841CMLU010665	Colour	METALLIC BLUE
	Odometer	47324 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	9 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	9 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/12/2024	Inspection Date	26/12/2024
	Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 9912E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOTLID	BENT	1,782.80	1,782.80
1	REAR BOOT EMBLEM	MTG DENTED	196.90	196.90
1	REAR BOOTLID AVANTE EMBLEM	NECESSARY	58.70	58.70
1	REAR BOOTLID CAMERA	MTG CRACKED	875.40	875.40
2	REAR BOOTLID REFLECTOR @\$402.90	CUT	805.80	805.80
1	REAR BOOTLID LOCK	DISTORTED	185.00	185.00
1	REAR BOOTLID TOP SPOILER	NECESSARY	291.80	291.80
1	REAR BOOTLID STRIKER	TO REPAIR SEE LABOUR	45.20	-
1	REAR BUMPER ASSY	BENT	495.60	495.60
1	REAR BUMPER REINFORCEMENT	CRACKED	378.30	378.30
2	REAR BUMPER REINFORCEMENT BRACKET @\$91.30	BENT	182.60	182.60
2	REAR BUMPER RETAINER @\$68.90	SERVICEABLE	137.80	-
1	REAR BUMPER LOWER	CRACKED	361.80	361.80
5	REAR BUMPER LOWER BRACKET @\$45.10	CRACKED	225.50	225.50
2	REAR BUMPER REFLECTOR @\$145.10	CRACKED	290.20	290.20
1	REAR END PANEL	BENT	569.40	569.40
1	REAR END PANEL TOP GARNISH	MTG DISTORTED	147.80	147.80
1	REAR PANEL SENSOR	NO SUCH PARTS	195.50	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,025.60	-
1	REAR SPARE TYRE TOP BOARD	SERVICEABLE	285.60	-
	LESS 20% DISCOUNT		-	-1,369.52
			8,537.30	5,478.08
<u>SPECIAL NETT ITEMS</u>				
1	REAR BOOTLID RUBBER (SN) (50%)	DENTED / DISTORTED	178.60	89.30
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	SCRATCHED / SHORTED	300.00	200.00
1	REAR NO. PLATE (SN)	DENTED	80.00	45.00
			608.60	384.30

Report Ref No. CD/LPC24120398/Kpa3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO REMOVE AND REFIT DAMAGED PARTS, CUT/WELD DAMAGED AREAS. INCLUSIVE OF THE REPAIR OF REAR BOOTLID STRIKER AND REAR SPARE TYRE PANEL.		1,000.00	700.00
	TO SPRAY PAINT ON AFFECTED AREAS.		1,200.00	800.00
	CHECK WIRING.		50.00	20.00
	TUFF COATING.		120.00	60.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		120.00	50.00
	TO REMOVE AND REFIT REAR GARNISHES ETC.		180.00	60.00
			2,670.00	1,690.00
GRAND TOTAL			11,815.90	7,552.38
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,000.00

Report Ref No. CD/LPC24120398/Kpa3q2(N)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMS 9912E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

