

# Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SMS 9912E

Date: 23.12.24

Not Authorized  
11pm & 6000p  
Recovery After Rain  
6days

## S/N Parts Description

Unit Price Amt

- 1 Rear bootlid
- 2 Rear bootlid emblem
- 3 Rear bootlid Avante emblem
- 4 Rear bootlid camera
- 5 Rear bootlid reflector X 2
- 6 Rear bootlid lock
- 7 Rear bootlid rubber
- 8 Rear bootlid top spoiler
- 9 Rear bootid striker
- 10 Rear bumper assy
- 11 Rear bumper reinforcement
- 12 Rear bumper reinforcement bracket X 2
- 13 Rear bumper retainer X 2
- 14 Rear bumper lower
- 15 Rear bumper lower bracket X 5
- 16 Rear bumper relector X 2
- 17 Rear end panel
- 18 Rear end panel top garnish
- 19 Rear panel sensor
- 20 Rear spare tyre panel
- 21 Rear spare tyre top board

	BH	\$1,782.80	✓
	my d.i	\$196.90	✓
	me	\$58.70	✓
	my cm	\$875.40	✓
	\$402.90	LT	\$805.80
	my	\$185.00	✓
89.305N	no d.i	\$178.60	5065N
	me	\$291.80	✓
	R	\$45.20	X
	BH	\$495.60	✓
	cm	\$378.30	✓
	\$91.30	BH	\$182.60
	\$68.90	R	\$137.80
	cm	\$361.80	✓
	\$45.10	cm	\$225.50
	\$145.10	cm	\$290.20
	BH	\$569.40	✓
	my d.i	\$147.80	✓
	NIP	\$195.50	X
	R	\$1,025.60	X
	Sm	\$285.60	X

208

## Special Nett

- 1 Rer bumper clips
- 2 Rear bumper reverse sensor
- 3 Rear No.plate

	me	\$50.00	✓
	Se R / Jhon	\$300.00	2065N
	De	\$80.00	455N

## Labour

- 1 To remove and refit damaged parts, cut/weld damaged areas.
- 2 To spray paint on affected areas.
- 3 Check wiring
- 4 Tuff coating
- 5 To remove and refit rear reverse sensor

\$1,000.00	7001
\$1,200.00	8001
\$50.00	201
\$120.00	601
\$120.00	501

6 To remove and refit rear ganishes etc.

\$180.00 606

---

\$2,670.00

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: