

ASS. REC. BY:

REF:

LPC/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMS 9912E

Yr Regn:

03, 20

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

Avarde

c.c

1591

Colour:

m. Blue

AC:

Insured / Std / NI / NA

Sp. Reading

47320

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RMH08410M0U 010665

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

R:

P5165R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

23/12/24

D.O.I.

26/12/2024

Survey held at

Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24 not ready, Bootlid jammed

30/12 LTR & 6000

Date/Time, File Pass to?

☐

Prell. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S - RS. SI

Fees

Others

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SMS 9912E

Date: 23.12.24

S/N Parts Description

Unit Price Amt

- 1 Rear bootlid
- 2 Rear bootlid emblem
- 3 Rear bootlid Avante emblem
- 4 Rear bootlid camera
- 5 Rear bootlid reflector X 2
- 6 Rear bootlid lock
- 7 Rear bootlid rubber
- 8 Rear bootlid top spoiler
- 9 Rear bootid striker
- 10 Rear bumper assy
- 11 Rear bumper reinforcement
- 12 Rear bumper reinforcement bracket X 2
- 13 Rear bumper retainer X 2
- 14 Rear bumper lower
- 15 Rear bumper lower bracket X 5
- 16 Rear bumper relector X 2
- 17 Rear end panel
- 18 Rear end panel top garnish
- 19 Rear panel sensor
- 20 Rear spare tyre panel
- 21 Rear spare tyre top board

Not Authorized
11 Sep & 60000
Money After Paint
6 days
 B1 \$1,782.80 ✓
 my no \$196.90 ✓
 m \$58.70 ✓
 my cm \$875.40 ✓
 \$402.90 Lr \$805.80 ✓
 89.30 N1 \$185.00 ✓
 101011 \$178.60 5025N ✓
 m \$291.80 ✓
 R \$45.20 X
 B1 \$495.60 ✓
 cm \$378.30 ✓
 \$91.30 B1 \$182.60 ✓
 \$68.90 R \$137.80 X
 cm \$361.80 ✓
 \$45.10 cm \$225.50 ✓
 \$145.10 cm \$290.20 ✓
 B1 \$569.40 ✓
 my D1 \$147.80 ✓
 N1P \$195.50 X
 R \$1,025.60 X
 S \$285.60 X

Special Nett

- 1 Rer bumper clips
- 2 Rear bumper reverse sensor
- 3 Rear No.plate

m \$50.00 ✓
 Sur/Bar \$300.00 2001N
 Du \$80.00 451N

Labour

- 1 To remove and refit damaged parts, cut/weld damaged areas. \$1,000.00 7001
- 2 To spray paint on affected areas. \$1,200.00 8001
- 3 Check wiring \$50.00 201
- 4 Tuff coating \$120.00 601
- 5 To remove and refit rear reverse sensor \$120.00 501

6 To remove and refit rear ganishes etc.

\$180.00 601

\$2,670.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: