

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

→ China
26 Dec 2024

Estimate No. : b1 72203
Date Estimated : 23/12/2024
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Sharmila Sripathy Mrs Sharmila Srip
22 CROWHURST DRIVE
SERANGOON GARDEN ESTATE

SINGAPORE 557901

- ACCOUNT - 40000
Cash Sales - Service
Singapore

MBLG

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS5775Y	WBY42AW050FT45643	01/08/2024	I4 EDRIIVE35 GRAN COUPE	18

DESCRIPTION

VALUE

Replace rear bumper and attachment etc and carryout necessary
repairing work
on accident damage area

850/ 1,275.00

Painting rear bumper

1,038.00

To remove and install rear boot compartment interior
carpet and garnish to facilitate the repair job
on rear section.

271.00

To check electrical wiring system and lighting at the
rear section for proper function.

177.00

Sundries nec

150.00

Total Labour 1: 2,911.00

DESCRIPTION	QTY	PRIC	VALUE
EXPANDING RIVET	10	2.70 x nn	27.00
REAR BUMPER PANEL PRIMED (PDC/PMA)	1	1,332.30 1362.90	1,332.30
REAR TOWING EYE COVER PRIMED	1	52.30	52.30
SET MOUNTING PDC/PMA SENSOR REAR	1	75.55	75.55
REAR BUMPER BOTTOM TRIM PANEL	1	253.80 259.65	253.80
REAR BUMPER MOUNTING	1	86.70	86.70
REAR BUMPER CARRIER	1	537.05	537.05
REAR BUMPER LH CORNER MOUNTING (M)	1	86.70	86.70
REAR BUMPER RH CORNER MOUNTING (M)	1	86.70	86.70
ADAPTER FOR SUPPORT REAR	1	218.85 223.90	218.85
REAR BUMPER LH MOUNT	1	177.55	177.55
REAR BUMPER RH MOUNT	1	177.55	177.55
REAR LH ACCENT STRIP (I BLUE)	1	184.35	184.35
REAR RH ACCENT STRIP (I BLUE)	1	184.35	184.35
Absorber fun	1	52.05	52.05
Absorber fun	1	52.05	52.05
Protective f	1	6.15	6.15
Protective foil	1	6.15	6.15

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 72203**
Date Estimated : **23/12/2024**
Prepared By : **Chua Kee Sin**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS5775Y	WBY42AW050FT45643	01/08/2024	I4 EDRIVE35 GRAN COUPE	18

DESCRIPTION	QTY	PRIC	VALUE
REAR LH REAR REFLECTOR	1	43.50	X 43.50
REAR RH REAR REFLECTOR	1	43.50	X 43.50
DECOUPLING RING	6	5.65	X 33.90
ULTRASONIC SENSOR BLACK	2	264.35	X 528.70
ULTRASONIC SENSOR BLACK	2	269.65	X 539.30
ULTRASONIC SENSOR BLACK SIDE	2	269.65	X 539.30
Total Parts :			5,325.35

Tanjim 97495749/62565561
WP' 14/1/250 1115
P/P Resurvey before paint
~3 days
Tanjim @hhando.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Labour 1	:	2,911.00
Parts	:	5,325.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	741.27
Grand Total	:	8,977.62

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **