

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

Xiao Teng

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16

AIG BUILDING, SINGAPORE 079120

TEL: 64193000

FAX: 68357416

ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party

Accident Date: 20/12/2024

TP Veh Reg No: SMP5412Z

Estimate No: EST2400535

Date: 26 Dec 2024

Veh Reg No: SMA1634E

Make/Model: TOYOTA VIOS E AUTO

Chasis No: MR2B23F3401121929

Reg. Date: 30/05/2018

Your Ref No: SMP5412Z

Estimate Repair Cost to Vehicle No :SMA1634E

Quantity	Description	List Price S\$	Amount S\$
List Price			
1	1 PC BOOT LID <i>Dented</i>	1,327.95	✓ 1040
2	1 PC BOOT LID LOGO <i>new</i>	66.90	✓
3	1 PC BOOT LID "VIOS" EMBLEM <i>new</i>	58.65	✓
4	1 PC BOOT LID "E" EMBLEM <i>new</i>	49.20	✓
5	1 PC BOOT LID LAMP RH <i>green</i>	412.24	+
6	1 PC BOOT LID LAMP LH <i>green</i>	412.24	+
7	1 PC BOOT LID LOCK <i>Dented</i>	602.88	✓ 560
8	1 PC BOOT LID LOCK CHECKER <i>new</i>	49.95	+
9	1 PC BOOT LID RUBBER <i>lt</i>	264.76	-
10	1 PC BOOT LID TRIM <i>new</i>	491.37	+
11	1 PC REAR PANEL <i>Dented</i>	1,236.60	985
12	1 PC REAR PANEL TRIM <i>Dented</i>	420.52	390
13	1 PC TAIL LAMP - RH <i>2 int</i>	955.49	780
14	1 PC TAIL LAMP LH <i>2 int</i>	955.49	780
15	1 PC REAR BUMPER <i>Dented</i>	891.62	✓
16	1 PC REAR BUMPER REINFORCEMENT <i>Dented</i>	558.52	420
17	2 PCS REAR BUMPER SIDE RETAINER <i>2 green</i>	517.90	330
18	2 PCS REAR BUMPER SMALL RETAINER <i>2 green</i>	199.26	+
19	1 PC REAR BUMPER REFLECTOR - RH <i>new</i>	141.59	+
<i>Antenna Sensor 285</i>		9.613.13	
<i>antenna</i>		2.403.28	7.209.87
Special Net			
20	1 PC BOOT LID "609" STICKER <i>new</i>	35.00	✓
21	1 SET BOOT LID TRIM CLIPS <i>new</i>	40.00	+
22	1 SET REAR PANEL TRIM CLIPS <i>new</i>	30.00	20
23	1 PC REAR FENDER STICKER RH <i>green</i>	290.00	+
24	1 PC REAR FENDER STICKER LH <i>green</i>	290.00	+
25	2 PCS "L" PLATE BRACKET <i>new</i>	140.00	90
26	1 SET REAR BUMPER CLIPS <i>new</i>	60.00	30
<i>Reas Bumper Strides</i>		885.00	885.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 20/12/2024
TP Veh Reg No: SMP5412Z

Estimate No: EST2400535
Date: 26 Dec 2024
Veh Reg No: SMA1634E
Make/Model: TOYOTA VIOS E AUTO
Chasis No: MR2B23F3401121929
Reg. Date: 30/05/2018
Your Ref No: SMP5412Z

Estimate Repair Cost to Vehicle No :SMA1634E

Quantity	Description	List Price S\$	Amount S\$
Labour			
27	1 TO CHECK WIRING	50.00	30
28	1 TO REPLACE STICKERS	80.00	50
29	1 TO SPRAY AND SEALANT	80.00	80
30	1 TO REFIX REAR INNER TRIM	80.00	80
31	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	800
32	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.	1,000.00	800
		2,290.00	2,290.00
		Total	S\$ 10,384.87
		Add GST @ 9%	934.64
		Total Amount Payable	S\$ 11,319.51

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND THREE HUNDRED NINETEEN AND CENTS FIFTY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

total: 7614.87
H/S: 6.1K
26/12/24
06/12/24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: