

Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16

AIG BUILDING, SINGAPORE 079120

TEL: 64193000

FAX: 68357416

ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party

Accident Date: 20/12/2024

TP Veh Reg No: SMP5412Z

Estimate No: EST2400535

Date: 26 Dec 2024

Veh Reg No: SMA1634E

Make/Model: TOYOTA VIOS E AUTO

Chasis No: MR2B23F3401121929

Reg. Date: 30/05/2018

Your Ref No: SMP5412Z

Estimate Repair Cost to Vehicle No :SMA1634E

Quantity	Description	List Price	Amount
		S\$	S\$
	List Price		
1	1 PC BOOT LID <i>Dented</i>		
2	1 PC BOOT LID LOGO <i>new</i>	1,327.95	✓
3	1 PC BOOT LID "VIOS" EMBLEM <i>new</i>	66.90	✓
4	1 PC BOOT LID "E" EMBLEM <i>new</i>	58.65	✓
5	1 PC BOOT LID LAMP RH <i>new</i>	49.20	✓
6	1 PC BOOT LID LAMP LH <i>new</i>	412.24	
7	1 PC BOOT LID LOCK <i>Dented</i>	412.24	
8	1 PC BOOT LID LOCK CHECKER <i>new</i>	602.88	✓
9	1 PC BOOT LID RUBBER <i>new</i>	49.95	✓
10	1 PC BOOT LID TRIM <i>new</i>	264.76	✓
11	1 PC REAR PANEL <i>Dented</i>	491.37	✓
12	1 PC REAR PANEL TRIM <i>Dented</i>	1,236.60	✓
13	1 PC TAIL LAMP - RH <i>new</i>	420.52	✓
14	1 PC TAIL LAMP LH <i>new</i>	955.49	✓
15	1 PC REAR BUMPER <i>Dented</i>	955.49	✓
16	1 PC REAR BUMPER REINFORCEMENT <i>Dented</i>	891.62	✓
17	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	558.52	✓
18	2 PCS REAR BUMPER SMALL RETAINER <i>new</i>	517.90	✓
19	1 PC REAR BUMPER REFLECTOR - RH <i>new</i>	199.26	✓
	Antenna Sensor 185 <i>new</i>	141.59	✓
		9.613.13	
	Less 25%	2,403.28	7,209.87
	Special Net		
20	1 PC BOOT LID "609" STICKER <i>new</i>	35.00	✓
21	1 SET BOOT LID TRIM CLIPS <i>new</i>	40.00	✓
22	1 SET REAR PANEL TRIM CLIPS <i>new</i>	30.00	✓
23	1 PC REAR FENDER STICKER RH <i>new</i>	290.00	✓
24	1 PC REAR FENDER STICKER LH <i>new</i>	290.00	✓
25	2 PCS "L" PLATE BRACKET <i>new</i>	140.00	✓
26	1 SET REAR BUMPER CLIPS <i>new</i>	60.00	✓
	Rear Bumper Strides <i>new</i>	885.00	885.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16

AIG BUILDING, SINGAPORE 079120

TEL: 64193000 FAX: 68357416

ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party

Accident Date: 20/12/2024

TP Veh Reg No: SMP5412Z

Estimate No: EST2400535

Date: 26 Dec 2024

Veh Reg No: SMA1634E

Make/Model: TOYOTA VIOS E AUTO

Chasis No: MR2B23F3401121929

Reg. Date: 30/05/2018

Your Ref No: SMP5412Z

Estimate Repair Cost to Vehicle No :SMA1634E

Quantity	Description	List Price	Amount
		S\$	S\$
	Labour		
27	1 TO CHECK WIRING	50.00	30
28	1 TO REPLACE STICKERS	80.00	50
29	1 TO SPRAY AND SEALANT	80.00	60
30	1 TO REFIX REAR INNER TRIM	80.00	60
31	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	800 Sav
32	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.	1,000.00	700
		2,290.00	2,290.00
	Total	S\$ 10,384.87	
	Add GST @ 9%		934.64
	Total Amount Payable		S\$ 11,319.51

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND THREE HUNDRED NINETEEN AND CENTS FIFTY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adrian L
26/12/24
06 Days