



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 ATTN: GERALD POH			Ref: CS/LPC24120401/Unh3m4(N) Date: 07/01/2025 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 6783T	Veh. Inspected	GBH 7342B
	Policy No.	Z24VC06115083	Coverage (\$)	0.00
	Claim No.	24/24/25/VC05/030358	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	26/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTFAT35Y60K211310	Colour	SILVER
	Odometer	265245 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195R15	FALKEN	6 mm
	L/H Front Tyre	195R15	FALKEN	6 mm
	R/H Rear Tyre	155R12 (D)	FALKEN	6/6 mm
	L/H Rear Tyre	155R12 (D)	FALKEN	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/12/2024	Inspection Date	27/12/2024
	Survey held at	SIN HOCK LEE MOTOR REPAIR 51 UBI AVENUE 1 #01-09 PAYA UBI INDUSTRIAL PARK . SINGAPORE 408933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days