

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24120403/EVP3M4
Date: 08/01/2025

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MZD03718		
Claimant Vehicle No :	SHA4558G	Insured Vehicle No :	GBL8830G		
Date of Loss:	25/12/2024	Nature of Claim:	TP	Claim No:	M2407559

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA4558G	Engine No:	2ZR3B88306
Make & Model:	TOYOTA PRIUS TAXI, 1.8 HATCHBACK(AT) (2WD) (A)	Chassis No:	JTDAE3AU703008541
Reg. Date:	30/09/2024 (Man. Year: 2024)	Odometer:	26514 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,086.18	2,621.48	464.70	15.06
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,655.00	1,095.00	560.00	33.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,753.18	3,728.48	1,024.70	21.56
+ GST 9.00/9.00% (S\$)	427.78	335.56	92.22	21.56
Nett Amount (S\$)	5,180.96	4,064.04	1,116.92	21.56

INSPECTION

Date of Assignment:	26/12/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang) COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969
Date Inspected:	27/12/2024	Inspected At:	
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2025)
Parts:	144	TOYOTA PRIUS TAXI 1.8 HATCHBACK(AT)(2WD) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA4558G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Broken	601.00 FL	*601.00 FL
2	1		*REAR BUMPER BEAM	Bent	451.50 FL	*451.50 FL
3	10		*REAR BUMPER CLIPS	Necessary	57.00 FL	*22.00 FL
4	1		*REAR BUMPER CENTRE MOULDING	Broken	779.00 FL	*779.00 FL
5	1		*TAILLAMP ASSY RH	Broken	984.50 FL	*984.50 FL
6	1		*REAR REFLECTOR RH	Broken	282.10 FL	*282.10 FL
7	1		*BOOTLID EMBLEM - PRIUS	Necessary	124.28 FL	*124.28 FL
8	1		*BOOTLID COMFORT LOGO	Necessary	30.00 F	*30.00 F
9	1		*BOOTLID COMFORT TEL.NOS LOGO	Necessary	30.00 F	*30.00 F
10	1		*BOOTLID APPS LOGO	Necessary	40.00 F	*40.00 F
11	1		*REVERSE SENSOR	Not Necessary	180.00 F	*- F
12	1		*BOOTLID EMBLEM - HEW	Necessary	70.00 FL	*70.00 FL
13	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	132.90 FL	*- FL
14	1		*REAR FENDER MOULDING RH	Not Necessary	211.70 FL	*- FL
Supplementary #1						
15	1		*TOW COVER - BUMPER LOWER	Broken	24.60 FL	*24.60 FL
16	1		*TOW COVER - BUMPER UPPER	Broken	23.00 FL	*23.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,021.58	3,461.98
- List Item Discount on L Items 25.00/25.00% (S\$)	935.40	840.50
Total Parts (S\$)	3,086.18	2,621.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	380.00
2	SPRAYPAINT CHARGES	New	600.00	560.00
3	CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	0.00
5	REMOVE/REFIX REVERSE SENSOR	New	50.00	20.00
6	TOWING CHARGES	New	105.00	105.00
Gross Labour Cost (\$\$)			1,655.00	1,095.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >