



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2502053

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN:KAREN TAN

INV Date 04/04/2025
Reference CD/FCI24120404/Upa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. FBS 4964T
Insured Veh. SHA 1185T
Claim No. D24011136MFCT/TPD2/KT
Policy No. D-24101861MFCT
Accident Date 19/12/2024
Inspection Date 24/12/2024

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (9%)	45.00
Grand Total	545.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



Your Ref : D24011136MFCT/TPD2/KT

Date: 04th April 2025

Our Ref : CD/FCI24120404/Upa3q2

MS FIRST CAPITAL INSURANCE LTD

16 RAFFLES QUAY

#42-01 HONG LEONG BUILDING

SINGAPORE 048581

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBS 4964T
INSURED VEHICLE SHA 1185T ACCIDENT ON 19/12/2024**

Instruction was received to inspect the vehicle Reg. No. FBS 4964T. The inspection was conducted on 24/12/2024 at the premises of M/s Ban Hock Hin Co. Pte Ltd, Blk 8 Defu South Street 1, #04-28 Jtc Defu Industria City, Singapore 533758 .

The following vehicle information was recorded:

Registration Number	: FBS 4964T
Make/Model	: HONDA NC750XA
Year of Registration	: 2015
Body Colour	: WHITE
Chassis Number	: JH2RC72B1EK007953
Engine Capacity	: 745 cc
Speedometer Reading	: 69321

The vehicle sustained damages at the front portion & o/s body. The Estimated repair cost of such vehicle is S\$7,250.00 (Sin Dollars: Seven Thousand Two Hundred and fifty only.) (Exclude check items S\$1,498.50 Nett) (Details see photographs enclosed)

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"uneconomical Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 2,000.00

Less: LTA Reimbursement Value (RV)

(S\$ 31.00)

Nett Liability

S\$ 1,969.00

S\$ 1,969.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 7,250.00

(Exclude check items S\$1,498.50Nett)

Nett Liability

S\$ 7,250.00

(a) – (b) =

(S\$ 5,281.00)

The amount of estimated saving of S\$5,281.00 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T





PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T




PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T




PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T




PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T




PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T





PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T




PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T



PHOTOGRAPHS FOR VEHICLE NO. : FBS 4964T

