



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2501019

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN:JOANNE YONG

INV Date 18/02/2025
Reference CD/FCI24120407/Epa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLM 2680M
Insured Veh. SHD 7066Z
Claim No. D24011031MFCT
Policy No. D-24101861MFCT
Accident Date 16/12/2024
Inspection Date 18/12/2024

Description	Total
Third Party Express Settlement	300.00
Subtotal	300.00
GST (9%)	27.00
Grand Total	327.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CD/FCI24120407/Epa3q2
16 RAFFLES QUAY	Date:	18/02/2025
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHD 7066Z	Veh. Inspected	SLM 2680M
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24011031MFCT	Excess	\$0.00
Assign From	JOANNE YONG	Assign Date	17/12/2024

2. Vehicle Details

Make & Model	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR	C.C	1197
Engine No.	HRA2402075A	Year of Reg.	25/03/2017
Chassis No.	SJNFEAJ11U1910376	Colour	SILVER
Odometer	137881 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORT RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60 R17	MICHELIN	6
L/H Front Tyre	215/60 R17	MICHELIN	6
R/H Rear Tyre	215/60 R17	MICHELIN	6
L/H Rear Tyre	215/60 R17	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/12/2024	Inspection Date	18/12/2024
Survey held at	DICKSON AUTO CARE CENTRE PTE LTD 29 UBI ROAD 4, DICKSON AUTO CENTRE, SINGAPORE 408619		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLM 2680M

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BUMPER REAR	DEFORMED	\$946.50	\$755.00
10	BUMPER CLIPS	NECESSARY	\$50.00	\$30.00
1	SENSOR REAR (SET)	SHORTED	\$250.00	\$250.00
1	TOW EYE COVER REAR RH	CUT	\$43.10	\$43.10
	LESS 10.00% DISCOUNT		(\$128.96)	(\$107.81)
			\$1,160.64	\$970.29

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & REPLACE BUMPER REAR & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT.		\$250.00	\$200.00
	TO SPRAY BUMPER REAR.		\$250.00	\$200.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$100.00	\$30.00
	TO TRANSFER ALL BUMPER REAR SENSOR.		\$200.00	\$30.00
			\$800.00	\$460.00

GRAND TOTAL		\$1,960.64	\$1,430.29
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$1,150.00
Report Ref No: CD/FCI24120407/Epa3q2			


CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SLM 2680M




PHOTOGRAPHS FOR VEHICLE NO. : SLM 2680M



PHOTOGRAPHS FOR VEHICLE NO. : SLM 2680M



PHOTOGRAPHS FOR VEHICLE NO. : SLM 2680M



PHOTOGRAPHS FOR VEHICLE NO. : SLM 2680M



PHOTOGRAPHS FOR VEHICLE NO. : SLM 2680M



PHOTOGRAPHS FOR VEHICLE NO. : SLM 2680M



PHOTOGRAPHS FOR VEHICLE NO. : SLM 2680M

