



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

Steve (LKK)
18/12/24, 11:30am
L/S
AL
3 days

QUOTATION

QUOTATION FOR

NAME: MS First Capital Insurance Ltd
COMPANY NAME: MS First Capital Insurance Ltd
STREET ADDRESS: 6 Raffles Quay, #21-00
POSTAL CODE: Singapore 048580
PHONE: 6222 2311

DATE: 17/12/2024

REF: SD0B24CG0005
VEHICLE NO: SLM2680M
MAKE: NISSAN
MODEL: QASHQAI
PREPARED BY: XIANG

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
LABOUR							
1	TO REMOVE & REPLACE BUMPER REAR & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	1		\$250.00	\$ 250.00		\$ 250.00 200
2	TO SPRAY BUMPER REAR	1		\$250.00	\$ 250.00		\$ 250.00 100
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	1		\$100.00	\$ 100.00		\$ 100.00 30
4	TO TRANSFER ALL BUMPER REAR SENSOR	1		\$200.00	\$ 200.00		\$ 200.00 30
PARTS							
1	BUMPER REAR / DEF	1		\$946.50	\$ 946.50		\$ 946.50
2	BUMPER CLIPS - MK	10		\$5.00	\$ 50.00		\$ 50.00 30
3	SENSOR REAR [SET] / shwtd	1		\$250.00	\$ 250.00		\$ 250.00
4	TOW EYE COVER REAR RH - cur	1		\$43.10	\$ 43.10		\$ 43.10
SUBTOTAL					\$ 2,089.60	SUBTOTAL	\$ 2,089.60
GST 9%					\$ 188.06	GST 9%	\$ 188.06
TOTAL					\$ 2,277.66	TOTAL	\$ 2,277.66

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD



(AUTHORISED SIGNATURE)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: