

REF:

ASSIGNMENT

From: _____ Date: _____

Estimate: _____

OD / TP RES / OD RES / EVA / INV / MVTo In Vehicle No: _____at W Work / s _____

ci _____

Insured: _____

Policy No _____

Claims No _____

Sum Insured _____ Excess: _____

(Client's Record)

Make of Vehicle _____

(Policy Condition)

Remarks: Vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Smx8685R Yr Regn: 2016 MarchType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Touran C.O. 1390Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 84717 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVG2221TZFW089115Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / I / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 27/12/24

Survey held at

JL PerfectDes. of Damages: Frt Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ATGCOE ExpiryEstimate given during: Yes ✓
1st Survey: No ✓

MV:

PV:

Nett:

262H

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + R.S. \$1

Photos

Others

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Inve (\$)

Report Format:

Report Form: _____

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 26.12.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMX8685R**
MODEL : **VOLKSWAGEN TOURAN**
DATE OF ACCIDENT : 18.12.2024
TIME OF ACCIDENT : 10:25 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE LOGO	1	\$ 132.00	\$ 132.00
2	TAILGATE EMBLEM 'TOURAN'	1	\$ 88.10	\$ 88.10
3	TAILGATE EMBLEM 'TDI'	1	\$ 81.90	\$ 81.90
4	TAILGATE INNER TRIM	1	\$ 468.70	\$ 468.70
5	TAILGATE TOP LOCK	1	\$ 157.10	\$ 157.10
6	TAILGATE LOWER LOCK	1	\$ 77.30	\$ 77.30
7	TAILGATE WEATHERSTRIP	1	\$ 429.30	\$ 429.30
8	TAIL LAMP	2	\$ 312.70	\$ 625.40
9	TAIL LAMP LOWER BRACKET	1	\$ 55.10	\$ 55.10
10	REAR BUMPER (UPPER)	1	\$ 1,188.60	\$ 1,188.60
11	REAR BUMPER LOWER CENTER	1	\$ 407.70	\$ 407.70
12	REAR BUMPER REFLECTOR	2	\$ 70.40	\$ 140.80
13	REAR BUMPER CENTER BEAM	1	\$ 217.60	\$ 217.60
14	REAR BUMPER SIDE RETAINER	2	\$ 46.20	\$ 92.40
15	REAR BUMPER REINFORCEMENT	1	\$ 657.80	\$ 657.80
16	REAR FENDER INNER TRIM	2	\$ 469.70	\$ 939.40
17	REAR FENDER INNER COWLING	2	\$ 206.80	\$ 413.60
18	REAR END PANEL	1	\$ 698.70	\$ 698.70
19	REAR END PANEL TOP GARNISH	1	\$ 169.40	\$ 169.40

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMX8685R**
 MODEL : **VOLKSWAGEN TOURAN**
 DATE OF ACCIDENT : 18.12.2024
 TIME OF ACCIDENT : 10:25 HOURS

20	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 770.00	\$ 770.00
21	REAR STORAGE BOX <i>could</i>	1	\$ 321.40	\$ 321.40

TOTAL PRICE \$ 8,132.30
 LESS 10% \$ 813.23
SUB TOTAL PRICE \$ 8,945.53

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (UPPER) (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
2	REAR BUMPER LOWER CENTER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
3	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
4	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
5	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
6	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
8	REVERSE SENSOR <i>Brand</i>	1	\$ 220.00	\$ 220.00

TOTAL \$ 620.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	600
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	40
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMX8685R**
MODEL : **VOLKSWAGEN TOURAN**
DATE OF ACCIDENT : 18.12.2024
TIME OF ACCIDENT : 10:25 HOURS

8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x
---	--	-----------	---

TOTAL \$ 4,520.00

TOTAL PARTS COST : \$ 9,565.53
TOTAL LABOUR COST : \$ 4,520.00
TOTAL REPAIR COST : \$ 14,085.53

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian
L/S 27/12/24
05 Days.