

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



**HD PERFECT
AUTOWORK PTE LTD**

DATE : 17.08..2023

TO : **CHINA TAIPING MOTOR CLAIMS DEPTS**
VEHICLE NO : **GBL1866A**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 06.12.2024
TIME OF ACCIDENT : 06:59 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR SIDE PANEL LH X R	1	\$ 1,828.90	\$ 1,828.90
2	REAR SIDE INNER LOWER PANEL LH X R	2	\$ 648.30	\$ 1,296.60
3	REAR SIDE INNER PANEL (BIG) LH X	2	\$ 1,584.30	\$ 3,168.60
4	REAR SIDE PANEL AIR VENT RH LH X	1	\$ 185.70	\$ 185.70
5	TAILGATE / DR	1	\$ 2,210.70	\$ 2,210.70
6	TAILGATE WINDSCREEN GLASS / DR	1	\$ 1,343.60	\$ 1,343.60
7	TAILGATE OUTER MOULDING X	1	\$ 364.90	\$ 364.90
8	TAILGATE OUTER HANDLE / CR	1	\$ 97.80	\$ 97.80
9	TAILGATE NUMBER PLATE LAMP X	2	\$ 65.50	\$ 131.00
10	TAILGATE LOGO / PK	1	\$ 70.50	\$ 70.50
11	TAILGATE DAMPER X	2	\$ 127.40	\$ 254.80
12	TAILGATE CORNER GARNISH X	2	\$ 185.90	\$ 371.80
13	TAILGATE STOPPER X	2	\$ 24.10	\$ 48.20
14	TAILGATE HINGE X	2	\$ 62.90	\$ 125.80
15	TAILGATE SIDE STOPPER X	2	\$ 28.60	\$ 57.20
16	TAILGATE INNER BOARD / CR	1	\$ 388.70	\$ 388.70
17	TAILGATE INNER TOP GARNISH X	1	\$ 215.60	\$ 215.60
18	TAILGATE WEATHERSTRIP / TR	1	\$ 397.80	\$ 397.80

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : GBL1866A
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 06.12.2024
 TIME OF ACCIDENT : 06:59 HOURS

19	TAILGATE WEATHERSTRIP PROTECTOR X	1	\$ 271.60	\$ 271.60
20	TAILGATE INNER LOCK / BT	1	\$ 354.60	\$ 354.60
21	TAILGATE INNER LOCK COVER GARNISH X	1	\$ 68.50	\$ 68.50
22	TAILGATE LOCK MOTOR X	1	\$ 545.00	\$ 545.00
23	TAILGATE LOCK OUTER HANDLE M / (UT)	1	\$ 15.20	\$ 15.20
24	TAILGATE LOWER LOCK X	1	\$ 254.10	\$ 254.10
25	TAILGATE THIRD BRAKE LAMP X	1	\$ 386.40	\$ 386.40
26	TAIL LAMP (LH) - (RT)	1/2	\$ 355.20	\$ 710.40
27	TAIL LAMP PANEL LH X	2	\$ 419.80	\$ 839.60
28	TAILLAMP LOWER GARNISH X	2	\$ 257.40	\$ 514.80
29	TAILLAMP LOWER GARNISH RETAINER X	2	\$ 53.70	\$ 107.40
30	TAILLAMP INNER PANEL LH X	1	\$ 488.50	\$ 488.50
31	REAR BUMPER / M	1	\$ 497.00	\$ 497.00
32	REAR BUMPER NUT COVER X	2	\$ 28.00	\$ 56.00
33	REAR BUMPER STEP PANEL / BT	1	\$ 384.60	\$ 384.60
34	REAR BUMPER SIDE RETAINER X	2	\$ 47.50	\$ 95.00
35	REAR END PANEL (EXTEND) X	1	\$ 428.10	\$ 428.10
36	REAR END PANEL (INNER) X	1	\$ 1,124.80	\$ 1,124.80
37	REAR END PANEL (OUTER) X	1	\$ 498.60	\$ 498.60

TOTAL PRICE \$ 20,198.40
 LESS 25% \$ 5,049.60
SUB TOTAL PRICE \$ 15,148.80

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE X	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) / M	1	\$ 50.00	\$ 50.00
3	REAR SIDE PANEL SEALANT (INNER) X	2	\$ 150.00	\$ 300.00
4	REAR SIDE PANEL SEALANT (OUTER) X	2	\$ 150.00	\$ 300.00
5	REAR SIDE PANEL GLASS SEALANT X	2	\$ 180.00	\$ 360.00
6	REAR SIDE PANEL GLASS INNER SHIELD X	2	\$ 120.00	\$ 240.00
7	TAIL LAMP CLIP (SET) X	1	\$ 30.00	\$ 30.00

30

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : GBL1866A
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 06.12.2024
 TIME OF ACCIDENT : 06:59 HOURS

8	TAILLAMP LOWER GARNISH CLIP (SET) ✓	1	\$ 30.00	\$ 30.00
9	TAILGATE CENTER MOULDING CLIP (SET) ✓	1	\$ 30.00	\$ 30.00
10	TAILGATE SEALANT ✗ / pc	1	\$ 150.00	\$ 150.00
11	TAILGATE TOP TRIM CLIP (SET) ✓	1	\$ 50.00	\$ 50.00
12	TAILGATE INNER TRIM CLIP (SET) ✗	1	\$ 50.00	\$ 50.00
13	TAIL GATE STICKER "HIACE" ✓ / pc	1	\$ 50.00	\$ 50.00
14	TAILGATE STICKER '70KM/H' ✓ / pc	1	\$ 30.00	\$ 30.00

TOTAL \$ 1,720.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 2,500.00	600
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00	500
3	WIRNING, BULB CHECKING	\$ 80.00	30
4	TRANSFER TAILGATE MECHAISM	\$ 80.00	50
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	✗
6	REMOVE AND REFIX ROOF LINING	\$ 100.00	✗
7	REMOVE AND REFIX REAR SIDE PANEL BOARD	\$ 200.00	✗
8	REMOVE AND REFIX SLIDING DOOR AND RAILWAY	\$ 200.00	✗
9	REMOVE AND REFIX REAR FLOOR TOP BOARD (WOODEN)	\$ 500.00	✗
10	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓

TOTAL \$ 5,900.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : GBL1866A
MODEL : TOYOTA HIACE
DATE OF ACCIDENT : 06.12.2024
TIME OF ACCIDENT : 06:59 HOURS

ESTIMATE REPORT

TOTAL PARTS COST : \$ 16,868.80
TOTAL LABOUR COST : \$ 5,900.00
TOTAL REPAIR COST : \$ 22,768.80

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP 8297 9787