



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GP 93P

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT CORNER PANEL RH	DENTED	\$190.00	\$190.00
	LESS 25.00% DISCOUNT		(\$47.50)	(\$47.50)
			\$142.50	\$142.50

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, REMOVAL AND REPLACING PARTS		\$200.00	\$100.00
	TO SPRAY PAINT AFFECTED AREA		\$200.00	\$100.00
			\$400.00	\$200.00

GRAND TOTAL			\$542.50	\$342.50
-------------	--	--	----------	----------

	RECOMMENDED COST OF REPAIRS (CONFIRMED)			\$342.50
--	--	--	--	----------

Report Ref No: CS/INC24070039/Anh3

TOTAL FOR SPARE PARTS: \$ 142.50 \$ 142.50
TOTAL FOR LABOUR : \$ 400.00 \$ 200.00
TOTAL REPAIR COST: \$ 542.50 \$ 342.50

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.