

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd
6 Raffles Quay
#22-00
Singapore 048580

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loganathan S/O Agoram

Date: 30 Dec 2024

Preliminary Advice

Vehicle No	: SMS7687T	Accident Date	: 25/12/2024
Make	: TOYOTA CAMRY	Policy No.	: D23MPCM000397
Assignment Date	: 27/12/2024	Excess	: S\$0.00
Date of Inspection	: 30/12/2024	Est. Duration of Repair	: 9
Inspection At	: OPTIMA WERKZ PTE LTD (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05/06 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,828.00
Revised Amount	:S\$	9,449.50
Check Items (Estimated)	:S\$	7,340.50
Total	:S\$	16,790.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	101,000.00
COE / PARF Rebate	:S\$	34,689.00
Salvage Value	:S\$	
Margin for Repair	:S\$	66,311.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on part by part basis due to no 2nd hand parts available. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.