

Date : 27/12/2024
Vehicle No: SMS7687T
Model: TOYOTA CAMRY HYBRID 2.5
Chassis: JTNB23HKX03055818-2019
Reg.Year: 2020
Policy No: D23MPCMO00397_1
Date of Accident: 25/12/2024
Estimator: TING AN

TO MOTOR CLAIM DEPT
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04/05/06-02 IOB BUILDING
SINGAPORE 049711

*Not withash
Punmy B4 pain
Ex @ 1500h
9 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1		Ry \$500.00
2	FRONT BONNET HINGE LH	1		D11 \$45.00
3	FRONT BONNET HINGE RH	1		R1 \$45.00
4	FRONT BONNET STRUT LH	1		\$130.00
5	FRONT BONNET STRUT RH	1		\$130.00
6	FRONT BONNET INSULATOR	1		\$200.00
7	FRONT BONNET LOCK	1		Tn \$75.00
8	FRONT UPPER GRILLE ASSEMBLY	1		CM \$380.00
9	FRONT HEADLAMP RH	1		Bo \$980.00
10	FRONT BUMPER	1		Tn \$300.00
11	FRONT BUMPER SIDE BRACKET RH	1		CM \$50.00
12	FRONT BUMPER LOWER GRILLE	1		CM \$300.00
13	FRONT BUMPER UNDER COVER	1		D11 \$220.00
14	FRONT BUMPER REINFORCEMENT	1		Ry \$175.00
15	FRONT BUMPER ABSORBER FOAM	1		CM \$60.00
16	FRONT WIPER WASHER TANK	1		Bro \$90.00
17	FRONT SUPPORT PANEL	1	\$690	Ry \$525.00
18	FRONT SUPPORT PANEL UPPER COVER	1		\$150.00
19	FRONT FENDER RH	1		Ry \$360.00
20	FRONT FENDER "HYBRID" EMBLEM	1		Am \$40.00
21	FRONT FENDER INNER SHIELD RH	1		CM \$100.00
22	FRONT FENDER AIR GUIDE RH	1		\$85.00
23	FRONT FENDER INNER PANEL RH	1		\$450.00
24	FRONT FENDER OUTER PANEL RH	1	\$550	Ry \$450.00
25	FRONT RIM RH	1		R \$1,900.00
26	FRONT ABSORBER RH	1	\$95	\$750.00
27	FRONT LOWER ARM RH	1		\$250.00
28	FRONT KNUCKLE ARM RH	1		\$260.00
29	FRONT WHEEL BEARING RH	1		\$300.00
30	FRONT STABILISER LINKAGE RH	1		\$85.00
31	FRONT TIE ROD END RH	1		\$85.00

Head office

8 Kung Chong Road Singapore 169143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-06 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

Date : 27/12/2024
Vehicle No: SMS7687T
Model: TOYOTA CAMRY HYBRID 2.5
Chassis: JTNB23HKX03055818-2019
Reg.Year: 2020
Policy No: D23MPCM000397_1
Date of Accident: 25/12/2024

TO MOTOR CLAIM DEPT
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04/05/06-02 IOB BUILDING
SINGAPORE 049711

32	FRONT STEERING RACK	1		\$2,280.00	7
33	FRONT CROSSMEMBER	1		\$1,200.00	7
34	FRONT DOOR RH	1		But \$700.00	✓
35	FRONT DOOR WEATHERSTRIP RH	1		Rn \$130.00	X
36	SIDE SKIRT RH	1		Bu \$400.00	✓
SUB TOTAL				\$14,180.00	\$11760
COST +10%				\$1,418.00	
PARTS TOTAL				\$15,598.00	\$12936

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BONNET INSULATOR CLIPS	1		Mu \$50.00	✓
2	FRONT BUMPER CLIPS	1		Mu \$50.00	✓
3	FRONT GRILLE CLIPS	1		Mu \$40.00	✓
4	FRONT NUMBER PLATE & HOLDER	1		Mu \$50.00	\$50.00
5	FRONT TYRE RH	1	\$90	Rn \$300.00	300.00
6	FRONT FENDER INNER SHIELD CLIPS RH	1		Mu \$40.00	✓
7	FRONT DOOR INNER TRIM BOARD CLIPS	1		\$50.00	7.20
S/N TOTAL				\$580.00	\$335

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

1200
\$2,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER RH, FRONT FENDER PANEL RH, FRONT DOOR RH, SIDE SKIRT RH & ETC.

1200
\$1,500.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MEACHNISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH.

\$120.00 600

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT KNUCKLE ARM RH, FRONT WHEEL BEARING RH, FRONT LOWER ARM RH, FRONT STEERING

\$500.00 2000

Date : 27/12/2024
Vehicle No: SMS7687T
Model: TOYOTA CAMRY HYBRID 2.5
Chassis: JTNB23HKX03055818-2019
Reg.Year: 2020
Policy No: D23MPCM000397_1
Date of Accident: 25/12/2024
RACK, FRONT CROSSMEMBER & ETC.

TO MOTOR CLAIM DEPT
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04/05/06-02 IOB BUILDING
SINGAPORE 049711

TO WHEEL ALIGNMENT & BALANCING.

\$80.00 ✓

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$120 \$300.00 ?

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$150.00 2d

LABOUR TOTAL \$4,650.00 \$2880

TING AN

TOTAL \$20,828.00

Head office

6 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 02/01/2025
Vehicle No: SMS7687T
Model: TOYOTA CAMRY HYBRID 2.5
Chassis: JTNB23HKX03055818-2019
Reg.Year: 2020
Policy No: D23MPCM000397_1
Date of Accident: 25/12/2024

TO MOTOR CLAIM DEPT
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04/05/06-02 IOB BUILDING
SINGAPORE 049711

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
✓ 1	FRONT DRIVESHAFT RH	1		\$780.00
✓ 2	FRONT BALL JOINT RH	1		\$90.00
✓ 3	CROSSMEMBER MOUNTING	4	\$75.00	\$300.00
✓ 4	HEADLAMP BALLAST RH	1		\$360.00
✓ 5	FRONT BUZZER	1		\$85.00
			SUB TOTAL	\$1,615.00
			COST +10%	\$161.50
			PARTS TOTAL	\$1,776.50 ✓

	TOTAL	\$1,776.50
--	--------------	-------------------

Finalise:

Parts: \$12936

Supp: \$1776.50

Nett: \$335

Labour: \$2880

P/P: \$17927.50