

Vehicle No: 465804
 Type: M.Cycle / Truck / Trailer or M.Cycle / M.Cycle / M.Cycle
 Make: M.P. White
 Colour: 1387
 A/C: T/Radio, Insurance
 3RC

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3 UEN: 199407592C

ESTIMATE

EST. No EST0036416
 Neo Yao Sheng

Page 1 of 2
 Your ref. TP-SNK 114G Somp
 Job No. 74898
 Our ref. 24.12.18
 Payment
 Date 23/12/2024

Attn

Vehicle No SLU 834H
 Vehicle Model : Mazda 5
 Accident on ... 18/12/2024

Not Withheld
 Murray Bypain
 Qdan

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear bumper	380.00		380.00 ✓
1.00	Pc	Rear bumper reinforcement	100.00		100.00 ?
1.00	Pc	Rear Mazda logo emblem	35.00		35.00 ✓
1.00	Pc	Rear Mazda emblem	22.00		22.00 ✓
1.00	Pc	Rear 5 emblem	18.00		18.00 ✓
1.00	Pc	Rear SKYACTIV emblem	38.00		38.00 ✓
1.00	Pc	Rear windscreen upper moulding	38.00		38.00 ✓
1.00	Pc	Tailgate	680.00		680.00 ✓
1.00	Pc	Tailgate garnish	200.00		200.00 ✓
Total amount of parts supplied-S\$1,511.00					
1.00		25% of parts supplied:	377.75		377.75
Special nett item:					
1.00	Set	Rear reverse camera+installation	250.00		250.00 ?
1.00	Set	Rear reversing sensor+installation	200.00		200.00 ✓

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理
 外, 还有先进的 SAICO Deluxe 喷漆烘炉。
 Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the supply
 olly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAI
 eluxe oven heater for re-spraying all motor vehicles."

Vehicle No: *SL00*
 Type: *Car* M.Cycle / Bus / Van
 Truck / Trailer or
 Make: *Testa*
 Colour: *M. P. white*
 1387
 A/C: Insured / Std / No.
 T/Radio: Insured / Std / No.
 465807

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

ESTIMATE

EST. No: EST0036416
 Neo Yao Sheng

Page: 2 of 2
 Your ref: TP-SNK 114G Somp
 Job No: 74898
 Our ref: 24.12.18
 Payment:
 Date: 23/12/2024

Attn:

Vehicle No: SLU 834H
 Vehicle Model: Mazda 5
 Accident on: 18/12/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Labour & Misc:					
1.00		To dismantle+refix rear windscreen	160.00		160.00 <i>120</i>
1.00		To supply sealant	40.00		40.00 ✓
1.00		To knock dents on rear end panel and renew parts	600.00		600.00 <i>400</i>
1.00		To spray paint	700.00		700.00 <i>450</i>

Sub-Total
 GST 9.00%
 Total
 S\$ 4,184.24

公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
 外，还有先进的 SAICO Deluxe 喷漆烘炉。
 Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support
 ally system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO
 Deluxe oven heater for re-spraying all motor vehicles."