



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 ATTN: THELMA CHOO			Ref: CS/SMO24120419/Knp3e2(N) Date: 23/04/2025 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNK 114G	Veh. Inspected	SLU 834H
	Policy No.	D24MTPV01009252	Coverage (\$)	0.00
	Claim No.	CMTD2404095/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	27/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 5 (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JM6CW1071H0127050	Colour	METALLIC DARK BLUE
	Odometer	144946 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	ARIVO	9 mm
	L/H Front Tyre	205/55 R16	ARIVO	9 mm
	R/H Rear Tyre	205/55 R16	FIRENZA	3 mm
	L/H Rear Tyre	205/55 R16	FIRENZA	3 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/12/2024	Inspection Date	30/12/2024
	Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	