



Liu Lu
315, Clementi Avenue 4, 10-141
Singapore 120315

Attention: Owner
Contact: 90040837

COMPLETE VMS PTE LTD

5 Soon Lee Street, #01-54, Pioneer Point, Singapore 627607
(Tel) 6555 6111 (Fax) 6554 0012 (Web) www.completevms.com.sg

The Premier One Stop Vehicle Accident Claims Centre

ESTIMATE

ES012615

Date 5/20/2025
Vehicle Number SKZ5611L
Make / Model B.M.W. 318i SEDAN LED NAV
Engine Number F1951252B38B15A
Chassis Number WBA8E36070NT39271
Accident Date Dec 1, 2024
Policy Number 5147224767

Description	Qty	Unit Price	Amount
-------------	-----	------------	--------

Parts

List Items

Rear Bumper	1	S\$1,342.60	S\$1,275.47 <i>de</i>
Rear Bumper Moulding	1	S\$262.30	S\$249.19 <i>at</i>
Rear Bumper Tow Cover	1	S\$85.70	S\$81.42 <i>x</i>
Rear Bumper Reflector L/H	1	S\$257.00	S\$244.15 <i>x</i>
Rear Bumper Reflector R/H	1	S\$257.00	S\$244.15 <i>x</i>
Rear Bumper Sponge	1	S\$147.60	S\$140.22 <i>x</i>
Rear Bumper Reinforcement	1	S\$572.30	S\$543.69 <i>x</i>

Discount 5% applied 1604.90
2,778.28

Special Nett Items

Bumper Clip	10	S\$6.50	S\$65.00 <i>300</i>
			30 \$65.00

Labour

To Remove & Refit Damage Part To Facilitate Repair	1	S\$1,000.00	S\$1,000.00 <i>200</i>
Spray Paint Damage Affect Area	1	S\$800.00	S\$800.00 <i>250</i>
		500	\$1,800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No liability modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total \$4,643.28

1524.65

30

500 450

2004.65

Pages 1/5 of 660 1/1

02 days #

COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which may be require after the work has begin