

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 48992400W

Vehicle Number: SLP2918M
Vehicle Model : Renault Megane GT Line 1.5DCI AT EU6
Chassis : VF1RFB00656602468
Year of Manufacture : 2016

not Authorised
 Mr
 Mera's
 27/12/24
 1/5 # 7200/
 Take photo After repair
 6 days

S/N.	Item Description	Amount (\$)
1	Rear Bumper <i>Torn</i>	\$ 1,420.14 ✓
2	Rear Bumper Rivet x 1 set <i>new</i>	\$ 50.00 ✓
3	Rear Bumper Side Bracket (Upper) (RH) <i>11</i>	\$ 236.53 X
4	Rear Bumper Side Bracket (Bottom) (RH) <i>202-00 CNe</i>	\$ 364.69 ✓
5	Rear Bumper Side Bracket Rivet x 6 pcs <i>11</i>	\$ 50.00 X
6	Taillamp (RH) <i>CNe</i>	\$ 562.18 ✓
7	Rear Fender (RH) <i>Body DO</i>	\$ 2,167.27 ✓
8	Rear Fender Inner Garnish (RH) <i>366 Torn</i>	\$ 400.75 ✓
9	Rear Fender Inner Garnish Clip x 1 set <i>11</i>	\$ 50.00 X
10	Diesel Tank Cover lock pump <i>Dange</i>	\$ 107.73 ✓
11	Diesel Tank Cover Bracket <i>CNe</i>	\$ 198.48 ✓
12	Rear Door (RH) <i>DO/Buf</i>	\$ 1,493.14 ✓
13	Rear Door Outer Handle (RH) <i>11</i>	\$ 352.08 X
14	Rear Door Trimboard Clip x 1 set <i>11</i>	\$ 50.00 X
15	Rear Shock Absorber (RH) <i>Sn</i>	\$ 377.04 X
16	Rear wheel hub bearing RH <i>Dange</i>	\$ 565.17 ✓
17	Rear Disc Rotor Protector (RH) <i>11</i>	\$ 498.80 X
Total :		\$ 8,944.00
Less 10% :		\$ 894.40
Amount :		\$ 8,049.60

S/N	Special Nett Item	Amount (\$)
1	Rear Tyre Rim (RH) <i>worped Bent</i>	\$ 1,400.00 6005/12 ✓
2	Rear Tyre (RH) <i>Seu</i>	\$ 180.00 X
3	Rear Fender Sealant <i>Sealant</i>	\$ 50.00 X
Amount :		\$ 1,630.00

Labour	Amount (\$)
To check electrical wiring system	\$ 80.00 20

To remove, and reinstall rear bumper sensors	\$ 120.00	30
To transfer door components from old door to new door	\$ 150.00	50
To remove & install diesel tank to facilitate repair	\$ 150.00	60
To remove & install rear windscreen to facilitate repair	\$ 150.00	X
To remove & install interior trims and garnishes to facilitate repair	\$ 180.00	60
To remove & install RHR undercarriages	\$ 280.00	120
To apply anti-rusting coating on affected panels	\$ 180.00	50
Labour to remove, cut, change & panel beating	\$ 1,500.00	800
To putty and respray affected areas	\$ 1,300.00	800
Labour Total :	\$ 4,090.00	
Total (Parts & Labour)	\$ 13,769.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-7132-11
10%
641890
600
1990
900890
202
7207