

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	NCE LTD		Ref:	CS/INC24120431/Uvh3e2(N)	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	09/01/2025	
	ATTN: ASTER QU	EK		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	PD 1726Y	Veh. Inspected		SLF 1728D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1309987-001	Excess (\$)		0.00	
	Assign From	ASTER QUEK	Assign Date		27/12/2024	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ B180 (A)	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	WDD2462422J390856	Colour		BROWN	
	Odometer	185156 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/40Z R18	PETLAS		6 mm	
	L/H Front Tyre	225/40Z R18	PETLAS		6 mm	
	R/H Rear Tyre	225/40Z R18	PETLAS		6 mm	
	L/H Rear Tyre	225/40Z R18	PETLAS		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
	DAMAGES SEE D	ETAILS.				
5.	General Information					
	Accident Date	26/12/2024	Inspect Date /	Time	27/12/2024 (10:11 AM)	
	Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD				
		1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883				
5a.	Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		6 Worki	ing Days	
	·					