

Date: 12/12/2024
Vehicle No: SMT2810G
Model: LEXUS UX200 5DR SUV
Chassis: JTHY35BH702021411-2019
Reg.Year: 2020

NOT Notified
Refusing B4palm
4 days

Third Party Insurer: CHINA TAIPING
Third Party Veh No: GBC3465H
Date of Accident: 29/11/2024
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR LH	1		<i>R</i> \$3,225.00
2	FRONT SIDE MIRROR ASSEMBLY LH	1		\$1,882.00
3	FRONT FENDER WHEEL ARCH LH	1		<i>h</i> \$506.00
4	FRONT RIM H	1		<i>del</i> \$4,002.00
5	FRONT ABSORBER LH	1		<i>h</i> \$1,040.00
6	FRONT KNUCKLE ARM LH	1		\$974.00
7	FRONT WHEEL BEARING LH	1		\$846.00
8	FRONT LOWER ARM LH	1		<i>h</i> \$1,458.00
9	FRONT FENDER LH	1		<i>/</i> REPAIR
SUB TOTAL				\$13,933.00
LESS 10%				-\$1,393.30
PARTS TOTAL				\$12,539.70

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR INNER TRIM BOARD LH CLIPS	1		<i>nn</i> \$50.00
2	FRONT FENDER WHEEL ARCH CLIPS LH	1		<i>na</i> \$40.00
S/N TOTAL				\$90.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$1,000.00 *3001*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT FENDER LH, FRONT DOOR LH & ETC.

\$500.00 *4001*

LABOUR CHARGES TO REMOVE & REINSTALL FRONT DOOR INNER MECHANISM & ETC.

nn \$120.00 *X*

LABOUR CHARGES TO REMOVE & REPLACE FRONT RIM LH, FRONT ABSORBER LH, FRONT KNUCKLE ARM LH, FRONT WHEEL BEARING LH, FRONT LOWER ARM LH & ETC.

\$400.00 *7*

TO WHEEL ALIGNMENT & BALANCING.

\$120.00 *201*

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 12/12/2024
Vehicle No: SMT2810G
Model: LEXUS UX200 5DR SUV
Chassis: JTHY35BH702021411-2019
Reg.Year: 2020

Third Party Insurer: CHINA TAIPING
Third Party Veh No: GBC3465H
Date of Accident: 29/11/2024
Estimator: TING AN
Surveyor:

TO DAIGNOSIS FAULT CODE & ETC.

\$150.00 7

TO CHECK WIRING & ELECTRICAL SYSTEM.


\$120.00 20/

LABOUR TOTAL \$2,410.00

TING AN

TOTAL

\$15,039.70



Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

