

Ding Auto Pte Ltd
Sin Ming Industrial Est. Sec C, Blk 10,#01-20
575645



Insurer Reference:
Repairer Reference: 074695
Date calculated: 23/12/2024 9:51 PM

Full Report
Registration: SNL7992L
Printed: 23/12/2024 9:51 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Ding Auto	Currency:	SGD
Claim Reference:		Date of Incident:	15/12/24
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	BMW
Model:	3-SERIES F30N
Sub Model:	330I
Model Sheet Number:	01 AF 06
Registration:	SNL7992L
VIN number:	WBA8A76040NU06833
Odometer:	109856

Model Specs

FROM 03.2016	LED FOG LAMPS	SPORT LINE	THROUGH LOAD SYSTEM
AIR CON AUTO 2-ZONES	WINDSCREEN RAIN SENS	COMPRESSION MODEL	O2 VOLUME
COMFORT ACCESS SYST	DIP REAR VIEW MIRROR	NAVIG SYST BUSINESS	HI-FI SPEAKER SYSTEM
LED HEADLAMP	LIGHT PACKAGE	DAKOTA LEATHER TRIM	FRT SPORT SEATS
HANDS FREE CONV SYST	ELEC/SEAT ADJ MEMORY	INSTR CLUSTER EXTEND	ALARM SWITCH
SHELF PACKAGE	FRT SLIDING ARMREST	CRUISE CONTROL	HEAD-UP DISPLAY
DIP REAR VIEW MIRROR	FRT/RR PARK DIST CON	REARVIEW CAMERA	1998CCM 185KW
SPORT S-WHEEL LEATH	8-SPEED AUTOMATIC	SERVOTRONIC	225/45-/255/40 R18 Y
WHEELS 8/8.5JX18 ALU	WINDOW FRAME BLACK	INT MOULDINGS ALUMIN	TWO COAT METALLIC
TYRE W/FLAT RUNNING			

Not Authorized
1/Rep &
Repair After Rain
5 days *Ex \$50k*

Insurer Reference:
Repairer Reference: 074695
Date calculated: 23/12/2024 9:51 PM

Full Report
Registration: SNL7992L
Printed: 23/12/2024 9:51 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right Middle), mm						Condition
	mm	mm	mm	mm	mm	mm	
Spare Tyre Brand	Tread (Spare), mm						

Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		2.0	7.00
41 35 555)	RENEW R/F WING		9.0	31.50
	INCLUDES: R + R WHEELHOUSE COVER			
	DOES NOT INCLUDE: R + R SILL MOULDING			
51 71 947	R + R R/SILL MOULDING		4.0	14.00
41 51 580	R + R RIGHT FRONT DOOR		3.0	10.50
67 62 505	R + R R/F WINDOW REGULATOR MOTOR		1.0	3.50
	(WINDOW REGULATOR REMOVED)			
41 52 580	R + R RIGHT REAR DOOR		3.0	10.50
41 51 563	ADJUST BOTH R/DOORS		4.0	14.00
41 51 562	RENEW BOTH R/DOORS (REMOVED)		72.0	252.00
51 22 830)	R + R R/R INNER WINDOW CHANNEL MOULDING		1.0	3.50
	DOES NOT INCLUDE: R + R DOOR TRIM			
67 62 525	R + R R/R WINDOW REGULATOR MOTOR		1.0	3.50
	(WINDOW REGULATOR REMOVED)			

Insurer Reference:
Repairer Reference: 074695
Date calculated: 23/12/2024 9:51 PM

Full Report
Registration: SNL7992L
Printed: 23/12/2024 9:51 PM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	8.30	100.0	350.00
Total of Labour			350.00

Paint

Paint Work		Time Basis 12 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
99 35 519	R/F WING PAINTING STAGE 2	7.0	24.50
99 51 548	RIGHT FRONT DOOR PAINTING STAGE 2	17.0	59.50
99 52 548	R/R DOOR PAINTING STAGE 2	14.0	49.00
99 99 000	ADDITIONAL TIME FOR ONE MAIN WORK INCLUDES: MIX COLOUR AND SPRAY COLOUR SAMPLE	21.0	73.50
Total Paint		4.90	59.0
			206.50

Material Cost - Paint	Price SGD
New Part Painting	140.00
Material-constant Metal	13.47
Total	153.47

Spare Parts

				prices as at 2024-05-17
Code	Description	Part Number	Part Source	Price SGD
1839	CLEANER R1 ✓	83 19 2 211 217		26.15 ✗
1837	QTR WINDOW SEAL KIT ✓	83 19 2 289 285		131.55 ✗
1510	R/F DOOR SEAL ✓	51 33 7 258 329	Original	180.00 ✗
0846	R/F LIP ✓	51 71 7 260 740	Original	95.00 ✗
0842	R/F WHEELHOUSE COVER ✓	51 71 7 260 726	Original	155.00 ✗
0844	R/F W-HOUSE RR COVER ✓	51 71 4 529 628	Original	125.00 ✗
1552	R/F WINDOW MOTOR ✓	67 62 7 406 624	Original	350.00 ✗
1548	R/F WINDOW REGULATOR ✓	51 33 7 281 886	Original	302.70 ✗
0742	R/F WING ✓	41 00 9 621 598	Original	820.00 ✓
1782	R/R DOOR ✓	41 00 7 298 514	Original	1,530.00 ✓
1810	R/R DOOR SEAL ✓	51 35 7 258 330	Original	230.00 ✓
1852	R/R WINDOW MOTOR ✓	67 62 7 341 564	Original	350.00 ✗
1848	R/R WINDOW REGULATOR ✓	51 35 7 281 888	Original	242.15 ✗
1482	RIGHT FRONT DOOR ✓	41 00 7 298 566	Original	1,530.00 ✓

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	6,067.55
Total	6,067.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Audatex System Using Manufacturer Times

Page 3 of 4

PRINT DATE 23/12/2024

Acknowledged by Repairer

Signature:

Date:

Insurer Reference:
Repairer Reference: 074695
Date calculated: 23/12/2024 9:51 PM

Full Report
Registration: SNL7992L
Printed: 23/12/2024 9:51 PM

Final Calculation

	SGD	SGD
Parts	6,067.55	
Total Parts		6,067.55
Labour Time Base 12 WU/h		
Total 100.0 WU X 42.00 SGD/h	343 350.00	
Total of Labour		350.00
Paint Work Time Base 12 WU/h		
Labour Cost 59.0 WU X 42.00 SGD/h	322 206.50	
Material Cost	✓ 153.47	
Total Paint Including Material		359.97
Repair Cost Excludes GST		6,777.52
GST (+9.00%)		609.98
Repair Cost Included GST		7,387.50
Deductions (Excludes GST)		
Deduction For Excess	-1,050.00	
Total Of Deductions (Excludes GST)		-1,050.00
Grand Total Excludes GST		5,727.52
GST (+9.00%)		515.48
Grand Total Included GST		6,243.00

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.