

ASSIGNMENT

From: _____ Date: _____
 Est: _____
 OD / TP RES / OD RES / EVA / INV / MV
 To In Vehicle No: _____
 at W/O 10/10/15
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____

Veh No: SNH9794T Yr Regn: 2018 Dec
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Vellfire CO: 2493
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 137660 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: AGH300201820
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/35 R 20
 R: 225/35 R 20

(Policy Condition)

Remarks: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Towrador

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 30/12/24
 Survey held at HD Perfect
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>7P ALG</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>Yes</u> <u>No</u>
	<u>Nett</u>
	<u>361C</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Report Form used:

Report Form used:

Company Reg No: 202136904Z

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com



**HD PERFECT
AUTOWORK PTE LTD**

DATE : 27.12.2024

TO	: AIG MOTOR CLAIMS DEPTS
VEHICLE NO	: SNN9794T
MODEL	: TOYOTA VELLFIRE
DATE OF ACCIDENT	: 26.12.2024
TIME OF ACCIDENT	: 16:15 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dented</i>	1	\$ 3,227.30	\$ 3,227.30
2	REAR BUMPER TOWING COVER <i>Rep</i>	2	\$ 42.80	\$ 85.60
3	REAR BUMPER REFLECTOR <i>RH Cracked</i>	2	\$ 123.90	\$ 247.80
4	REAR BUMPER SIDE INNER GARNISH LH <i>NEW</i>	1	\$ 290.70	\$ 290.70
5	REAR BUMPER SIDE INNER GARNISH RH <i>Dented</i>	1	\$ 138.50	\$ 138.50
6	REAR BUMPER SIDE RETAINER <i>NEW</i>	2	\$ 165.80	\$ 331.60
7	REAR BUMPER MUDFLAP <i>NEW</i>	2	\$ 125.00	\$ 250.00
8	REVERSE SENSOR <i>2 pieces damaged</i>	4	\$ 419.70	\$ 1,678.80
9	REVERSE SENSOR RING HOLDER <i>NEW</i>	4	\$ 49.80	\$ 199.20
10	REVERSE SENSOR CLIP <i>NEW</i>	4	\$ 25.30	\$ 101.20
11	REVERSE SENSOR WIRE HARNESS <i>NEW</i>	1	\$ 388.60	\$ 388.60
12	TAILGATE <i>Dented</i>	1	\$ 4,585.00	\$ 4,585.00
13	TAILGATE OUTER MOULDING (CHROME) <i>Cracked</i>	1	\$ 1,532.00	\$ 1,532.00
14	TAILGATE LAMP <i>Cracked</i>	2	\$ 975.60	\$ 1,951.20
15	TAILGATE INNER AUTO SWITCH BUTTON <i>NEW</i>	1	\$ 187.90	\$ 187.90
16	TAILGATE OUTER SWITCH BUTTON <i>NEW</i>	1	\$ 228.40	\$ 228.40
17	TAILGATE NUMBER PLATE LAMP <i>NEW</i>	2	\$ 89.40	\$ 178.80
18	TAILGATE WIRE HARNESS <i>NEW</i>	1	\$ 355.80	\$ 355.80
19	TAIL GATE LOGO <i>NEW</i>	1	\$ 98.20	\$ 98.20
20	TAIL GATE EMBLEM 'VELLFIRE' <i>NEW</i>	1	\$ 99.50	\$ 99.50
21	TAILGATE LOCK DETECTOR <i>Cracked</i>	1	\$ 325.00	\$ 325.00
22	TAILGATE LOCK DETECTOR WIRE HARNESS <i>NEW</i>	1	\$ 298.60	\$ 298.60

TO	: AIG MOTOR CLAIMS DEPTS
VEHICLE NO	: SNN9794T
MODEL	: TOYOTA VELLFIRE
DATE OF ACCIDENT	: 26.12.2024
TIME OF ACCIDENT	: 16:15 HOURS

23	TAIL GATE LOCK BUZZER	new	1	\$ 228.50	\$ 228.50
24	TAIL GATE DAMPER	new	2	\$ 125.60	\$ 251.20
25	TAILGATE AUTO SIDE SENSOR LH	RH Del'd	2	\$ 1,555.70	\$ 3,111.40
26	TAILGATE TOP LOCK	Damaged	1	\$ 1,351.00	\$ 1,351.00
27	TAILGATE LOWER LOCK	new	1	\$ 59.40	\$ 59.40
28	TAILGATE HINGE	new	2	\$ 87.90	\$ 175.80
29	TAILGATE INNER TRIM LOWER	Cracked	1	\$ 2,122.30	\$ 2,122.30
30	TAILGATE INNER SIDE TRIM	3 new	2	\$ 158.60	\$ 317.20
31	TAILGATE INNER TOP TRIM	new	1	\$ 288.80	\$ 288.80
32	TAILGATE INNER HOLDER	new	1	\$ 98.40	\$ 98.40
33	TAILGATE WEATHER STRIP	new	1	\$ 520.80	\$ 520.80
34	TAILGATE STOPPER	new	4	\$ 35.60	\$ 142.40
35	TAILGATE WINDSCREEN C/W MOULDING	new	1	\$ 1,985.60	\$ 1,985.60
36	REAR FENDER RH	Repair	1	\$ 2,455.00	\$ 2,455.00
37	REAR FENDER INNER TRIM	RH cracked	2	\$ 2,322.40	\$ 4,644.80
38	REAR FENDER INNER COWLING	new	2	\$ 236.80	\$ 473.60
39	REAR FENDER QUARTER GLASS C/W MOULDING RH	new	1	\$ 865.30	\$ 865.30
40	REAR AIR CON BLOWER MOTOR	new Del'd	1	\$ 3,299.00	\$ 3,299.00
41	TAILLAMP	Cracked	2	\$ 1,138.60	\$ 2,277.20
42	TAILLAMP PANEL (OUTER)	3 Repair	2	\$ 368.20	\$ 736.40
43	TAILLAMP PANEL (INNER)		2	\$ 335.20	\$ 670.40
44	TAILLAMP PANEL (INNER) LOWER	Repair	2	\$ 327.10	\$ 654.20
45	REAR CORNER PANEL	RH Del'd	2	\$ 582.30	\$ 1,164.60
46	REAR CORNER PANEL RETAINER	new	2	\$ 142.10	\$ 284.20
47	REAR END PANEL	Dented	1	\$ 1,985.30	\$ 1,985.30
48	REAR END PANEL TOP GARNISH	Del'd	1	\$ 245.60	\$ 245.60
49	REAR FLOOR PANEL TOP BOARD (SIDE)	RH Del'd	2	\$ 982.10	\$ 1,964.20
50	REAR FLOOR PANEL TOP BOARD (CENTER)	Del'd	1	\$ 587.20	\$ 587.20
51	REAR FLOOR MAT	new	1	\$ 986.50	\$ 986.50
52	REAR FLOOR PANEL TRAY (CENTER)	new	1	\$ 452.30	\$ 452.30
53	REAR SEAT RAILWAY (CENTER)	new	2	\$ 1,865.00	\$ 3,730.00
54	REAR SEAT RAILWAY CENTER COVER GARNISH	new	2	\$ 395.20	\$ 790.40
55	REAR SEAT RAILWAY CENTER COVER GARNISH JOINT	new	4	\$ 65.30	\$ 261.20
56	REAR EXHAUST PIPE	Bent	1	\$ 1,860.00	\$ 1,860.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNN9794T**
 MODEL : **TOYOTA VELLFIRE**
 DATE OF ACCIDENT : 26.12.2024
 TIME OF ACCIDENT : 16:15 HOURS

57	REAR EXHAUST INSULATOR <i>Neu</i>	1	\$ 325.00	\$ 325.00	+
58	REAR EXHAUST MOUNTING <i>Neu</i>	2	\$ 48.50	\$ 97.00	+
59	REAR EXHAUST GASKET <i>Neu</i>	1	\$ 68.20	\$ 68.20	+
60	REAR SPARE TYRE BOLT <i>Neu</i>	1	\$ 86.20	\$ 86.20	+
61	REAR SPARE TYRE HOLDER GARNISH <i>Neu</i>	1	\$ 583.60	\$ 583.60	+
62	REAR SPARE TYRE COVER <i>Neu</i>	1	\$ 85.60	\$ 85.60	+
63	REAR CHASSIS EXTEND MEMBER RH <i>Rys</i>	1	\$ 869.10	\$ 869.10	+

TOTAL PRICE \$ 59,934.60
 LESS 25% \$ 14,983.65
SUB TOTAL PRICE \$ 44,950.95

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
2	REAR BUMPER CLIPS (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	30
3	REAR BUMPER LOWER LID (SPECAIL TYPE) <i>Delid</i>	1	\$ 2,000.00	\$ 2,000.00	850 1200
4	TAILGATE SEALANT <i>Neu</i>	1	\$ 150.00	\$ 150.00	+
5	TAILGATE INNER TRIM CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	30
6	TAILGATE INNER SIDE TRIM CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
7	TAILGATE WINDSCREEN SEALANT <i>3 Neu</i>	1	\$ 80.00	\$ 80.00	40
8	TAILGATE WINDSCREEN INNER SEAL <i>Neu</i>	1	\$ 60.00	\$ 60.00	30
9	TAIL GATE WINDSCREEN SOLAR FILM <i>Neu</i>	1	\$ 650.00	\$ 650.00	+
10	TAILGATE SPOILER CLIP <i>Neu</i>	1	\$ 50.00	\$ 50.00	+
11	TAILLAMP CLIPS (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00	+
12	TAILLAMP PANEL (OUTER) SEALANT <i>3</i>	2	\$ 80.00	\$ 160.00	+
13	TAILLAMP PANEL (INNER) SEALANT <i>XHP</i>	2	\$ 80.00	\$ 160.00	+
14	TAILLAMP PANEL (INNER) LOWER SEALANT <i>Neu</i>	2	\$ 80.00	\$ 160.00	+
15	REAR FENDER RH SEALANT <i>Neu</i>	1	\$ 120.00	\$ 120.00	+
16	REAR FENDER INNER TRIM CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	30
17	REAR FENDER INNER COWLING CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
18	REAR FENDER QUARTER GLASS SEALANT RH <i>3</i>	1	\$ 60.00	\$ 60.00	+
19	REAR FENDER QUARTER GLASS INNER SEAL RH <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
20	REAR FENDER QUARTER GLASS SOLAR FILM RH <i>Neu</i>	1	\$ 350.00	\$ 350.00	+
21	REAR END PANEL SEALANT <i>Neu</i>	1	\$ 150.00	\$ 150.00	60

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNN9794T**
 MODEL : **TOYOTA VELLFIRE**
 DATE OF ACCIDENT : 26.12.2024
 TIME OF ACCIDENT : 16:15 HOURS

22	REAR END PANEL TOP GARNISH CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00 <i>20</i>
23	REAR SEAT RAILWAY CENTER COVER GARNISH CLIP (SET) <i>HP</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
24	REAR SEAT RAILWAY CENTER COVER GARNISH JOINT CLIP (SET) <i>HP</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
25	TRIANGLE BREAKDOWN SIGN <i>New</i>	1	\$ 180.00	\$ 180.00 <i>+</i>
26	REAR EXHAUST PIPE (SET)(SPECAIL TYPE) <i>Best</i>	1	\$ 580.00	\$ 580.00 <i>250</i>

TOTAL \$ 5,720.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,000.00	<i>900</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>1000</i>
3	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 650.00	<i>60</i>
4	TUFF COAT	\$ 250.00	<i>60</i>
5	REMOVE AND REPLACE REAR WIREHARNESS	\$ 480.00	<i>X</i>
6	REMOVE & REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 350.00	<i>X</i>
7	REMOVE AND REFIX REAR FENDER QUARTER GLASS	\$ 100.00	<i>X</i>
8	REMOVE AND REFIX REAR RAILWAY RH	\$ 150.00	<i>X</i>
9	REMOVE & REFIX REVERSE SENSOR & DISTANCE SETTING	\$ 80.00	<i>50</i>
10	REMOVE & REFIX REVERSE CAMERA & DISTANCE SETTING	\$ 80.00	<i>50</i>
11	REMOVE AND REFIX REAR AIRCON BLOWER AND REFILL AIRCON GAS	\$ 350.00	<i>X</i>

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNN9794T**
MODEL : **TOYOTA VELLFIRE**
DATE OF ACCIDENT : 26.12.2024
TIME OF ACCIDENT : 16:15 HOURS

12	REAR CHASSIS ALIGNMENT	\$ 250.00	x
13	REMOVE & REFIX AND RESET TAILGATE AUTO SYSTEM	\$ 450.00	200.
14	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
15	REMOVE & REFIX VIDEO RECORDER	\$ 180.00	60.
16	REMOVE & REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
17	REMOVE AND REFIX REARSAFETY BELT	\$ 180.00	x
18	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
19	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	60
20	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 450.00	x

TOTAL \$ 7,810.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 50,670.95
TOTAL LABOUR COST : \$ 7,810.00
TOTAL REPAIR COST : \$ 58,480.95

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling
1/5 30/12/24
08 Days.