

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 13 Jan 2025

Preliminary Advice

Insured Vehicle No	: FBU4824D	Accident Date	: 26/12/2024
TP Vehicle No	: SNG4246D	Assignment Date	: 30/12/2024
Make	: TOYOTA C-HR HYBRID	Est. Duration of Repair	: 3
Date of Inspection	: 08/01/2025		
Inspection At	: BLUWEL AUTOMOTIVE SERVICE PTE LTD (HQ) 1 KAKI BUKIT AVENUE 6, #01-28/37/53/55/56 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,031.07
Revised Amount	:S\$	2,011.78
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,011.78
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	43,000.00
COE / PARF Rebate	:S\$	21,434.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,566.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 (X) Part-by-Part repair
 () Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.