



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: NEO JIE SI			Ref: CS/FCI24120439/Uvp3m4(N) Date: 16/01/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4882P	Veh. Inspected	SHC 4218C	
Policy No.	D-24101860MFCT	Coverage (\$)	0.00	
Claim No.	D25000067MFCT	Excess (\$)	0.00	
Assign From	EILEEN WANG	Assign Date	27/12/2024	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU003576216	Colour	MAROON	
Odometer	680557 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65R15	GREENTRAC	6 mm	
L/H Front Tyre	195/65R15	GREENTRAC	6 mm	
R/H Rear Tyre	195/65R15	GREENTRAC	6 mm	
L/H Rear Tyre	195/65R15	GREENTRAC	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/12/2024	Inspection Date	30/12/2024	
Survey held at	STRIDES PREMIER AUTOMOTIVE SERVICES PL 23 CHANGI SOUTH AVE 2 SINGAPORE 486443			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		