

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/FC124/20439/4v3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SHC 4218Cat Workshop m/s Strides premier

of _____

Insured: SHB 4882?

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C3691C
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SHC 4218C

Yr Regn:

12/12/17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA / Hybrid

Make:

Toyota prius

c.c

1798

Colour

maroon

A/C:

Insured / Std / NI / NA

Sp. Reading

680537

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU003576216Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65-15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

green trac

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

26/12/24

D.O.I.

30/12/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Case under 11-12-2025 LTA 87040

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	369K

Vehicle Details

Vehicle No.:	SHC4218C
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS111894
Chassis No.:	JTDKB3FU003576216
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	12 Dec 2017
First Registration Date:	12 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2025
PARF Rebate Amount:	\$3,000.00

Intended COE Rebate Details

COE Expiry Date:	11 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$4,040.00
Total Rebate Amount:	\$7,040.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Dec 2024

OK

SMRT Accident Vehicle Repair Estimates

the Repairer of the following:

- To resurvey before/after spray painting
 - To display damaged parts
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHC4218C
Case Reference Number	TAX/12/24/2089
Registration Date	12/12/17
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHIA HUNG KIANG
Type of Accident	Side Swipe
Accident Date and Time	26/12/24 1:25 AM
Accident Reported Date and Time	26/12/24 1:21 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	ACGJ24120072
Special Instruction to ARC, if any	DAMAGE TO REAR LEFT OF TAXI TOWED IN
Prepared Date and Time	26/12/24 3:00 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,018.00	\$0.00
Total Spray Cost	\$2,234.00	\$0.00
Total Spare Part Cost	\$7,082.53	\$0.00
Total Other Cost	\$916.00	\$0.00
TOTAL COST	\$11,250.53	\$0.00
Lump Sum Total	\$11,250.00	\$0.00
Number of Repair Days	8.0	
Prepared / Adjusted By	Mun San #	
ARC / Surveyor Sign Off Date		
Signature	sw	x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

not Authorized
in means
90096608

30/1/24 2/55

S-day 5
Tule pho - HLE 142

SMRT Accident Vehicle Repair Estimates

SMRT Auto
60 Woodlands I
FAX Number :
Estimator Telep
Accident Repor

Date Generate
User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION LH	\$1,018.00	200
Total Labour	\$1,018.00	800

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY TAIL GATE	\$378.00	200
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$220.00	100
TO RESPRAY REAR BUMPER	\$378.00	200
TO RESPRAY BUMPER BEAM	\$220.00	11 X
TO RESPRAY REAR END PANEL	\$220.00	100
TO RESPRAY REAR SPARE TYRE PANEL	\$220.00	11 X
TO RESPRAY REAR FENDER LH	\$378.00	200
TO RESPRAY FILLER RR BUMPER LH	\$220.00	50
Total Spray Painting & Panel Beating	\$2,234.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	3.11 ?
TO WASH AND VACUUM	\$60.00	17 X
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	60
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	11 X
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	20
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	50
TO REMOVE AND REFIX REAR WINDSCREEN	\$120.00	✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	30
TO REPLACE SUNDRY PARTS	\$100.00	11 X
Total Other Costs	\$916.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Appr
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace	D.S. —
		5202347030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace	Surf —
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace	re —
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace	re —
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$4.30	25.00	\$6.45	Replace	re —
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace	D.S. —
		5259968030	STOPPER, RR BUMPER, RH & LH	1.00	\$4.80	25.00	\$3.60	Replace	11 X
		5257647040	RETAINER, RR BUMPER, LH	1.00	\$127.40	25.00	\$95.55	Replace	11 X
		5259247040	SEAL, RR BUMPER, LH	1.00	\$95.50	25.00	\$71.63	Replace	Surf —
		5216116010	CLIPS PIECE, FRT BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	re —
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	D.S. —
		5256647900	FILLER, RR BUMPER, LH	1.00	\$168.60	25.00	\$126.45	Replace	Torn —
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Surf X

SMRT Accident Vehicle Repair Estimates

SMRT Automo
60 Woodlands I
FAX Number :
Estimator Telep
Accident Repor

Date Generate

User ID

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Appr
		9018906029	REAR BUMPER GROMMET SCREW	2.00	\$2.20	25.00	\$3.30	Replace	me ✓
		8156147151	LENS & BODY, REAR COMBINATION LAMP, LH	1.00	\$489.00	25.00	\$366.75	Replace	me X
		8159147010	LENS & BODY ASSY, RR BUMPER, LH	1.00	\$544.40	25.00	\$408.30	Replace	Cue ✓
		8149847020	COVER, REAR COMBINATION LAMP, LH	1.00	\$69.90	25.00	\$52.43	Replace	me X
		5839947030	COVER, REAR FLOOR UNDER, LH	1.00	\$261.60	25.00	\$196.20	Replace	me X
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$943.10	25.00	\$707.33	Replace	me X
		6563847060	LINER, REAR FENDER, LH	1.00	\$151.10	25.00	\$113.32	Replace	me X
		6700547440	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$1,238.40	25.00	\$928.80	Replace	me ✓
		6788147050	TAIL GATE WEATHERSTRIP, BACK DOOR	1.00	\$402.50	25.00	\$301.88	Replace	me X
		5611750140	TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1.00	\$31.10	25.00	\$23.33	Replace	me X
		7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1.00	\$992.30	25.00	\$744.22	Replace	Cue ✓
		7544147090	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace	me ✓
		7544247130	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace	me ✓
		6810547291	TAIL GATE GLASS SUB-ASSY, BACK DOOR	1.00	\$1,795.00	25.00	\$1,346.25	Replace	me X
		6480147031	TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1.00	\$821.20	25.00	\$615.90	Replace	me X
			SEALANT W/SCREEN (3PCS)	3.00	\$37.00	0.00	\$111.00	Replace S/N	me ✓
		6881047061	TAIL GATE BACK DOOR HINGE ASSY, RH & LH	2.00	\$66.20	25.00	\$99.30	Replace	me X
		7540348010	EMBLEM SUB-ASSY REAR	1.00	\$77.40	25.00	\$58.05	Replace	me X
			STICKER LOGO (TAILGATE))	2.00	\$25.00	0.00	\$50.00	Replace S/N	me ✓
		5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$707.10	25.00	\$530.33	Replace	me ✓
		5831147130	SPARE TYRE PANEL, PAN, REAR FLOOR	1.00	\$630.30	25.00	\$472.72	Replace	me X
			SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace S/N	me ✓
Total					\$11,499.00		\$8,890.16		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Chec
Total									

P-5369.5
 252
 4027.13
 202
 3221.71
 198
 1930