

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0953/2024/EQ
DATE : 30-Dec-24
WIP : 43326

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : M/S JADA MARINE TRADE & CONSULTANT PTE LTD
ADDRESS : 2 VENTURE DRIVE
#16-32
VISION EXCHANGE
SINGAPORE 608526

TELEPHONE : HP +65 96985835
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070137233-03
VEHICLE NO : **SMV 2418 X**
MODEL CODE : AUDI Q8 3.0 TFSI QU
MODEL YEAR : 22/9/2020
ENGINE NO : DCB 127910
CHASSIS NO : WAUZZZF13KD043757
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Dec-24
PLACE OF ACCIDENT : CARPARK HILTON SINGAPORE ORCHARD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 2418 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO SET UP AND PLACE VEHICLE IN ALUMINIUM BAY.	S/N \$	1,800.00	✓
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
3	TO REMOVE AND TRANSFER RHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	450.00 300	
4	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,800.00	✓
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOFLINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,800.00	✓
6	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,200.00 4200 = 600 x 7 4800	
SUBTOTAL LABOUR CHARGES		: \$	<u><u>13,410.00</u></u>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 2418 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, REAR END PANELLING, ROOF CHANNEL, RHS SILL PANEL, DOOR ENTRANCE, DRAIN CHANNEL, BOTH REAR WHEEL ARCH TRIMS, RHS REAR DOOR LOWER COVER, RHS REAR DOOR ARCH TRIM AND RHS REAR DOOR HANDLE.	\$	4100 8,300.00	5.5 x 600 = 3300 Wheel Arch x 2 = 400 Door Cover x 2 = 400 Door Handle 100 4200
8	TO CARRY OUT ALUMINIUM PRIMER WORKS.	S/N \$	900.00 ✓	
9	TO RENEW RHS 1/4 GLASS AND CARRY OUT WATER SEEPAGE TEST.	S/N \$	500.00 180 ✓	
10	TO INSTALL SOLAR FILM FOR RHS 1/4 GLASS.	S/N \$	400.00 ✓	
11	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00 ✓	
12	TO CARRY OUT DIAGNOTIC CHECK.	S/N \$	292.00 ✓	
TOTAL LABOUR CHARGES		:	\$ 24,082.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2418 X

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	REAR BUMPER <i>lit</i>	1	\$ 1,641.00	✓	1312.80	
2	REAR BUMPER GUIDE SECTION - RH <i>lit</i>	1	\$ 94.00	+		
3	REAR FENDER - RH <i>Dented</i>	1	\$ 10,844.00	✓	8675.20	
4	REAR FUEL INSERT <i>lit</i>	1	\$ 127.00	+		
5	FUEL FILLER NECK STICKER <i>lit</i>	1	\$ 38.00	+		
6	REAR QUARTER GLASS - RH <i>lit</i>	1	\$ 1,190.00	✓	952	
7	REAR WHEEL HOUSING LINER <i>lit</i>	1	\$ 424.00	+		
8	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>lit</i>	1	\$ 86.00	+		
9	REAR SPOILER <i>lit</i>	1	\$ 65.00	+		
10	REAR WHEEL COVER - LH / RH <i>Nec LIT, RH Missing</i>	2	\$ 892.00	✓	712.8	
11	REAR DOOR - RH <i>Dented</i>	1	\$ 5,945.00	✓	4756	
12	REAR DOOR OUTER SEAL - RH BOTTOM <i>✓ Nec</i>	1	\$ 214.00	✓	170.8	
13	BONDING AGENT <i>2 new</i>	1	\$ 54.00	2		
14	CLEANING SOLUTION <i>2 new</i>	1	\$ 92.00	2		
15	APPLICATOR <i>2 new</i>	1	\$ 10.00	2		
16	REAR DOOR OUTER SEAL - RH REAR <i>✓ nec</i>	1	\$ 315.00	✓	251.6	
17	REAR DOOR OUTER SEAL - RH FRONT <i>2 new</i>	1	\$ 238.00	2		
18	REAR DOOR CATCH - RH <i>✓ nec</i>	1	\$ 154.00	✓	122.8	
19	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 235.00	X		
20	REAR DOOR WHEEL COVER - RH <i>lit</i>	1	\$ 232.00	✓	185.2	
SUB TOTAL SPARE PARTS			\$ 22,890.00			

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2418 X

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
21	REAR DOOR COVER - RH <i>Alor</i>	1	\$ 603.00	✓	482.4	
22	REAR DOOR EXTERIOR HANDLE - RH <i>Cut</i>	1	\$ 412.00	✓	329.2	
23	REAR DOOR HANDLE CAP - RH <i>Regt</i>	1	\$ 56.00	+		
24	REAR DOOR HANDLE UNDERLAY - RH FRONT & REAR <i>NT</i>	2	\$ 15.00	+		
25	REAR DOOR HANDLE HOUSING <i>Alor</i>	1	\$ 24.00	+		
26	REAR DOOR HANDLE MOUNTING BAR - RH <i>Alor</i>	1	\$ 163.00	+		
27	REAR ROOF FRAME SEAL - RH <i>NT</i>	1	\$ 193.00	+		
28	REAR SILL PANEL SEAL - RH <i>NT</i>	1	\$ 315.00	✓ nec	251.6	
29	REAR WHEEL COVER - RH <i>NT</i>	1	\$ 138.00	×		
30	REAR ALUMINIUM RIM - RH <i>Cut</i>	1	\$ 4,217.00	✓	3373.6	
31	REAR ALUMINIUM RIM RUBBER VALVE <i>Alor</i>	1	\$ 5.00	+		
32	2-PACK EPOXY ADHESIVE <i>2 m</i>	1	\$ 182.00	✓ X		
33	ALUMINIUM POWDER	1	\$ 685.00	✓	548	
34	HARDENER	1	\$ 244.00	✓	195.2	
35	1/4 GLASS SEALANT	S/N	\$ 100.00	✓	100	
36	METAL FILTER POWDER	S/N	\$ 280.00	✓	280	
37	ACRYLIC SEALANT	S/N	\$ 180.00	✓	180	
38	STONE CHIP	S/N	\$ 180.00	✓	180	
39	CAVITY WAX	S/N	\$ 140.00	✓	140	
40	SUNDRIES <i>✓ nec</i>		\$ 1,000.00	✓	143.52	
TOTAL SPARE PARTS			:	\$	32,022.00	
TOTAL LABOUR CHARGES			:	\$	24,082.00	
GRAND TOTAL			:	\$	56,104.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King
SURVEYED DATE : 31/12/24.
AUTHORISED DATE :
EXCESS COST : 14 days
LIABILITY :
REMARKS : Not Authorised, 14 days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Hui Pong

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0953/2024/EQ

24-Feb-25

GLORY

1 of 1

SMV 2418 X

AUDI Q8 3.0 TFSI QU

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	RHS SILL TRIM STRIP <i>Nec</i>	\$ 771.00	✓ 616.8
2	COUNTERSUNK RIVET "ORDER QTY 100" <i>} Nec</i>	80 \$ 200.00	✓ 160
3	2-PACK EPOXY ADHESIVE	2 \$ 365.00	✓ 292
GRAND TOTAL		\$ 1,336.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Adrian Limy.
S.S. Resurveyed.