

ASSIGNMENT

From: _____ Date: _____

Estimate: _____

OD / TP / RES / OD RES / EVA / INV / MV

To In _____ Vehicle No: _____

at W _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured _____ Excess: **1400**

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remarks: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: **14** days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time _____ Action / Instruction

00 ALG

COE Expiry: _____

Estimate given during: Yes C /
1st Survey: No C /

MV: **240K**

PV: **101.8K**

Nett: **138.9K**

We will be advising our principal a cost of repair of \$41,843.52 before excess \$1,400 & GST with 14 repair days, subject to their approval.
(red, \$15596.48, 27%)

Date/Time, File Pass to? _____

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: _____

Report Format: _____

Veh No: **Smv2 418x** Yr Regn: **2020, Sept**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Audi Q8** O.D. **2995**

Colour: **Black** A/C: Insured / Std / NI / N/A

Sp. Reading: **52742** T/Radio: Insured / Std / NI / N/A

Eng/No: _____

C/No: **WAUZZZF13KD043757**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **285/45R21**

R: **285/45R21**

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Continental**

Front _____ Rear _____

R/Bal. **ab** mm R/Bal. **ab** mm

L/Bal. **ab** mm L/Bal. **ab** mm

D.O.A. _____ D.O.I. **31/12/24**

Survey held at **Premium**

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to? _____

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: _____

Report Format: _____

Days Of Repair: **14**

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invt (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + R.S. \$ _____

Photos _____

Others _____

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0953/2024/EQ
DATE	:	30-Dec-24
WIP	:	43326

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME	:	M/S JADA MARINE TRADE & CONSULTANT PTE LTD
ADDRESS	:	2 VENTURE DRIVE
		#16-32
		VISION EXCHANGE
		SINGAPORE 608526

TELEPHONE	:	HP +65 96985835
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070137233-03
VEHICLE NO	:	SMV 2418 X
MODEL CODE	:	AUDI Q8 3.0 TFSI QU
MODEL YEAR	:	22/9/2020
ENGINE NO	:	DCB 127910
CHASSIS NO	:	WAUZZZF13KD043757
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	26-Dec-24
PLACE OF ACCIDENT	:	CARPARK HILTON SINGAPORE ORCHARD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 2418 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO SET UP AND PLACE VEHICLE IN ALUMINIUM BAY.	S/N \$	1,800.00	✓
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
3	TO REMOVE AND TRANSFER RHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	450.00 300	
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,800.00	✓
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOFLINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,800.00	✓
6	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,200.00 4200 = 600 x 7	
SUBTOTAL LABOUR CHARGES		:	\$ 13,410.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 2418 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, REAR END PANELLING, ROOF CHANNEL, RHS SILL PANEL, DOOR ENTRANCE, DRAIN CHANNEL, BOTH REAR WHEEL ARCH TRIMS, RHS REAR DOOR LOWER COVER, RHS REAR DOOR ARCH TRIM AND RHS REAR DOOR HANDLE.	\$ 8,300.00 ⁴¹⁰⁰	$5.5 \times 600 = 3300$ Wheel Arch x 2 = 400 Door Cover x 2 = 400 Door Handle 100 - <u>4200</u>
8	TO CARRY OUT ALUMINIUM PRIMER WORKS.	S/N \$ 900.00 ✓	
9	TO RENEW RHS 1/4 GLASS AND CARRY OUT WATER SEEPAGE TEST.	S/N \$ 500.00 ¹⁸⁰	✓
10	TO INSTALL SOLAR FILM FOR RHS 1/4 GLASS.	S/N \$ 400.00 ✓	
11	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00 ✓	
12	TO CARRY OUT DIAGNOTIC CHECK.	S/N \$ 292.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>24,082.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2418 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>lt</i>	1	\$ 1,641.00	✓
2	REAR BUMPER GUIDE SECTION - RH <i>new</i>	1	\$ 94.00	+
3	REAR FENDER - RH <i>Dented</i>	1	\$ 10,844.00	✓
4	REAR FUEL INSERT <i>new</i>	1	\$ 127.00	+
5	FUEL FILLER NECK STICKER <i>new</i>	1	\$ 38.00	+
6	REAR QUARTER GLASS - RH <i>new</i>	1	\$ 1,190.00	✓
7	REAR WHEEL HOUSING LINER <i>new</i>	1	\$ 424.00	+
8	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 86.00	+
9	REAR SPOILER <i>new</i>	1	\$ 65.00	+
10	REAR WHEEL COVER - LH / RH <i>Need LH, RH Missing</i>	2	\$ 892.00	✓
11	REAR DOOR - RH <i>Dented</i>	1	\$ 5,945.00	✓
12	REAR DOOR OUTER SEAL - RH BOTTOM ?	1	\$ 214.00	?
13	BONDING AGENT ?	1	\$ 54.00	?
14	CLEANING SOLUTION ?	1	\$ 92.00	?
15	APPLICATOR ?	1	\$ 10.00	?
16	REAR DOOR OUTER SEAL - RH REAR ?	1	\$ 315.00	?
17	REAR DOOR OUTER SEAL - RH FRONT ?	1	\$ 238.00	?
18	REAR DOOR CATCH - RH ?	1	\$ 154.00	?
19	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 235.00	X
20	REAR DOOR WHEEL COVER - RH <i>lt</i>	1	\$ 232.00	✓
SUB TOTAL SPARE PARTS		:	\$ 22,890.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2418 X

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR DOOR COVER - RH <i>Not</i>	1	\$ 603.00	✓	
22	REAR DOOR EXTERIOR HANDLE - RH <i>Not</i>	1	\$ 412.00	✓	
23	REAR DOOR HANDLE CAP - RH <i>Not</i>	1	\$ 56.00	+	
24	REAR DOOR HANDLE UNDERLAY - RH FRONT & REAR <i>Not</i>	2	\$ 15.00	+	
25	REAR DOOR HANDLE HOUSING <i>Not</i>	1	\$ 24.00	+	
26	REAR DOOR HANDLE MOUNTING BAR - RH <i>Not</i>	1	\$ 163.00	+	
27	REAR ROOF FRAME SEAL - RH <i>Not</i>	1	\$ 193.00	+	
28	REAR SILL PANEL SEAL - RH <i>Not</i>	1	\$ 315.00	+	
29	REAR WHEEL COVER - RH <i>?</i>	1	\$ 138.00	?	
30	REAR ALUMINIUM RIM - RH <i>Not</i>	1	\$ 4,217.00	✓	
31	REAR ALUMINIUM RIM RUBBER VALVE <i>Not</i>	1	\$ 5.00	+	
32	2-PACK EPOXY ADHESIVE <i>Not</i>	1	\$ 182.00	✓	
33	ALUMINIUM POWDER <i>Not</i>	1	\$ 685.00	✓	
34	HARDENER <i>Not</i>	1	\$ 244.00	✓	
35	1/4 GLASS SEALANT <i>Not</i>	S/N	\$ 100.00	✓	
36	METAL FILTER POWDER <i>Not</i>	S/N	\$ 280.00	✓	
37	ACRYLIC SEALANT <i>Not</i>	S/N	\$ 180.00	✓	
38	STONE CHIP <i>Not</i>	S/N	\$ 180.00	✓	
39	CAVITY WAX <i>?</i>	S/N	\$ 140.00	✓	
40	SUNDRIES <i>?</i>		\$ 1,000.00	?	
TOTAL SPARE PARTS		:	\$ 32,022.00		
TOTAL LABOUR CHARGES		:	\$ 24,082.00		
GRAND TOTAL		:	\$ 56,104.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *31/12/24*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 14 days*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT