

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0953/2024/EQ
DATE : 30-Dec-24
WIP : 43326

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian,

14 Days + 2 Sun - OK - Allan Boo

7-Apr-25

OWNER'S NAME : M/S JADA MARINE TRADE & CONSULTANT PTE LTD
ADDRESS : 2 VENTURE DRIVE
#16-32
VISION EXCHANGE
SINGAPORE 608526

TELEPHONE : HP +65 96985835
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070137233-03
VEHICLE NO : **SMV 2418 X**
MODEL CODE : AUDI Q8 3.0 TFSI QU
MODEL YEAR : 22/9/2020
ENGINE NO : DCB 127910
CHASSIS NO : WAUZZZF13KD043757
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Dec-24
PLACE OF ACCIDENT : CARPARK HILTON SINGAPORE ORCHARD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 2418 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO SET UP AND PLACE VEHICLE IN ALUMINIUM BAY.	S/N \$	1,800.00	\$ 1,800.00
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$ 360.00
3	TO REMOVE AND TRANSFER RHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	450.00	\$ 300.00
4	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,800.00	\$ 1,800.00
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOFLINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,800.00	\$ 1,800.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,200.00	\$ 4,800.00
SUBTOTAL LABOUR CHARGES		:	\$ 13,410.00	\$ 10,860.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 2418 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
				\$ 10,860.00
7	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, REAR END PANELLING, ROOF CHANNEL, RHS SILL PANEL, DOOR ENTRANCE, DRAIN CHANNEL, BOTH REAR WHEEL ARCH TRIMS, RHS REAR DOOR LOWER COVER, RHS REAR DOOR ARCH TRIM AND RHS REAR DOOR HANDLE.	\$	8,300.00	\$ 4,200.00
8	TO CARRY OUT ALUMINIUM PRIMER WORKS.	S/N \$	900.00	\$ 900.00
9	TO RENEW RHS 1/4 GLASS AND CARRY OUT WATER SEEPAGE TEST.	S/N \$	500.00	\$ 500.00
10	TO INSTALL SOLAR FILM FOR RHS 1/4 GLASS.	S/N \$	400.00	\$ 400.00
11	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$ 280.00
12	TO CARRY OUT DIAGNOTIC CHECK.	S/N \$	292.00	\$ 292.00
TOTAL LABOUR CHARGES		:	\$ 24,082.00	\$ 17,432.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2418 X

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 1,641.00	\$	1,312.80
2	REAR BUMPER GUIDE SECTION - RH	1	\$ 94.00		
3	REAR FENDER - RH	1	\$ 10,844.00	\$	8,675.20
4	REAR FUEL INSERT	1	\$ 127.00		
5	FULEL FILLER NECK STICKER	1	\$ 38.00		
6	REAR QUARTER GLASS - RH	1	\$ 1,190.00	\$	952.00
7	REAR WHEEL HOUSING LINER	1	\$ 424.00		
8	REAR WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 86.00		
9	REAR SPOILER	1	\$ 65.00		
10	REAR WHEEL COVER - LH / RH	2	\$ 892.00	\$	712.80
11	REAR DOOR - RH	1	\$ 5,945.00	\$	4,756.00
12	REAR DOOR OUTER SEAL - RH BOTTOM	1	\$ 214.00	\$	170.80
13	BONDING AGENT	1	\$ 54.00		
14	CLEANING SOLUTION	1	\$ 92.00		
15	APPLICATOR	1	\$ 10.00		
16	REAR DOOR OUTER SEAL - RH REAR	1	\$ 315.00	\$	251.60
17	REAR DOOR OUTER SEAL - RH FRONT	1	\$ 238.00		
18	REAR DOOR CATCH - RH	1	\$ 154.00	\$	122.80
19	REAR DOOR ATTACHMENT PARTS	1	\$ 235.00		
20	REAR DOOR WHEEL COVER - RH	1	\$ 232.00	\$	185.20
SUB TOTAL SPARE PARTS		:	\$ 22,890.00	\$	17,139.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2418 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 17,139.20
21	REAR DOOR COVER - RH	1 \$	603.00	\$ 482.40
22	REAR DOOR EXTERIOR HANDLE - RH	1 \$	412.00	\$ 329.20
23	REAR DOOR HANDLE CAP - RH	1 \$	56.00	
24	REAR DOOR HANDLE UNDERLAY - RH FRONT & REAR	2 \$	15.00	
25	REAR DOOR HANDLE HOUSING	1 \$	24.00	
26	REAR DOOR HANDLE MOUNTING BAR - RH	1 \$	163.00	
27	REAR ROOF FRAME SEAL - RH	1 \$	193.00	
28	REAR SILL PANEL SEAL - RH	1 \$	315.00	\$ 251.60
29	REAR WHEEL COVER - RH	1 \$	138.00	
30	REAR ALUMINIUM RIM - RH	1 \$	4,217.00	\$ 3,373.60
31	REAR ALUMINIUM RIM RUBBER VALVE	1 \$	5.00	
32	2-PACK EPOXY ADHESIVE	1 \$	182.00	
33	ALUMINIUM POWDER	1 \$	685.00	\$ 548.00
34	HARDENER	1 \$	244.00	\$ 195.20
35	1/4 GLASS SEALANT	S/N \$	100.00	\$ 100.00
36	METAL FILTER POWDER	S/N \$	280.00	\$ 280.00
37	ACRYLIC SEALANT	S/N \$	180.00	\$ 180.00
38	STONE CHIP	S/N \$	180.00	\$ 180.00
39	CAVITY WAX	S/N \$	140.00	\$ 140.00
	ADD PARTS - SUPPLEMENTARY			\$ 1,068.80
40	SUNDRIES	\$	1,000.00	\$ 143.52
TOTAL SPARE PARTS			\$ 32,022.00	\$ 24,411.52
TOTAL LABOUR CHARGES			\$ 24,082.00	\$ 17,432.00
GRAND TOTAL			\$ 56,104.00	\$ 41,843.52

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0953/2024/EQ 24-Feb-25 GLORY 1 of 1 SMV 2418 X AUDI Q8 3.0 TFSI QU
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	RHS SILL TRIM STRIP	\$ 771.00	\$ 616.80
2	COUNTERSUNK RIVET "ORDER QTY 100"	80 \$ 200.00	\$ 160.00
3	2-PACK EPOXY ADHESIVE	2 \$ 365.00	\$ 292.00
GRAND TOTAL		\$ 1,336.00	\$ 1,068.80

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT