

Not Whose
1 Rm @ 600h
1 day

VEHICLE DETAILS

VEHICLE NO : SNL7612J

MODEL : TOYOTA SIENTA

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>718.60 od/cut</i>	1	\$ 1,896.00	\$ 1,896.00
2	FRONT BUMPER LOWER GRILLE <i>PL</i>	1	\$ 284.20	\$ 284.20
3	FRONT BUMPER LOWER GRILLE CHROME <i>PL</i>	1	\$ 321.00	\$ 321.00
4	FRONT BUMPER SIDE GARNISH RH <i>PL</i>	1	\$ 351.20	\$ 351.20
5	FRONT BUMPER SIDE RETAINER <i>PL</i>	1	\$ 59.10	\$ 59.10
6	LED HEADLAMP WITH DRL RH <i>PL</i>	1	\$ 2,758.60	\$ 2,758.60
7	HEADLAMP BRACKET RH <i>PL</i>	1	\$ 150.60	\$ 150.60

TOTAL PRICE \$ 5,820.70
LESS 25% \$ 1,455.18
SUB TOTAL PRICE \$ 4,365.53

S/N

1	FRONT BUMPER CLIPS SET <i>me</i>	1	\$ 75.00	\$ 75.00
---	----------------------------------	---	----------	----------

TOTAL \$ 75.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	CUT OFF AND REPLACE FRONT SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS.	\$ 500.00		<i>180</i>
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 500.00	<i>nn</i>	<i>X</i>
3	ADJUST AND FOCUS FRONT LED LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	\$ 120.00	<i>nn</i>	<i>X</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature

4	REMOVE AND INSTALL FRONT PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY INPUT TESTING.	\$ 180.00		
---	---	-----------	--	--