

Sin Motor Repairs

Block 176, #05-07, Sin Ming Drive, Sin Ming Auto Care
Singapore 575721

Tel: 64533908, 64596902 Fax: 64536602

G.S.T. REGISTRATION : 07683000D

T/P ESTIMATE - 129/SM

AGAINST YOUR INSURED VEHICLE NO. YP412P

THIRD PARTY INSURANCE: LONPAC INSURANCE SINGAPORE - 62507388

THE INSURED / DRIVER :

MR LIM BOON CHERN

BLK 984B BUANGKOK LINK

#14-23 SINGAPORE

MP : 9766 6778

SING LIFE LTD INSURANCE

POLICY NO. 13274673

VEHICLE NO. SJY8118S

DATE OF ACCIDENT : 30/12/2024- AM

ALONG ROAD

SINGAPORE

MODEL : BMW 520I

CHASIS NO. WBA5A32070D829428

- 1) REAR BOOT LID 1850
- 2) REAR BUMPER 1616
- 3) REAR BUMPER LOWER PANEL
- 4) REAR BUMPER SIDE RETINDER - LH
- 5) REAR TAIL LAMP LH
- 6) REAR BOOT LAMP LH
- 7) REAR BUMPER - REINFORCEMENT 774.30
- 8) REAR BUMPER INNER END PANEL
- 9) REAR BUMPER BRACKETS - 2PCS @\$230*2
- 10) BUMPER CLIPS @ \$8*15PCS
- 11) REAR REVERSE SENSORS - 2PCS @\$285*2/1

R	2,054.00	✓
Bu	1,682.00	✓
R	138.00	X
R	229.00	X
R	752.00	X
W	443.00	✓
R	943.00	✓
R	1,345.00	X
R	460.00	X
R	120.00	500
R	570.00	4

SUB-TOTAL :

8,736.00

LESS 10% DISCOUNT

-873.60

7,862.40

LABOUR CHARGES FOR THE FOLLOWING :- NETT

WHEEL ALIGNMENT

85.00 } 450

TO DISMANTLE N RE-FIXING - REAR BOOT, 2PCS LAMP/ RR BUMPER/ SENSOR
SUPPORT AND ABOVE

720.00 }

TO DETECT PARKING SENSOR

80.00 601

SPRAY PAINTING ON REAR BUMPER, RR BOOT LID AND LOWER PANEL

850.00 500

(PEARL WHITE)

9,597.40

959.74

10,557.14

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification
- Supplementary items must be approved and is subject to final approval from Insurance Company

SUB-TOTAL :

ADD 10% G.S.T

G-TOTAL :

Acknowledged by Repairer

Signature:

Date: