

**SMRT Accident Vehicle Repair Estimates**

<b>SMRT Automot</b>
60 Woodlands I
FAX Number :
Estimator Telep
Accident Repor

Date Generate

User ID

TP  
84

Great American

**Section A - Accident Details**

Registration Number	SHD6428U
Case Reference Number	TAX/12/24/2092
Registration Date	19/12/17
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	SIM KWANG IMK
Type of Accident	Side Swipe
Accident Date and Time	27/12/24 9:20 AM
Accident Reported Date and Time	27/12/24 2:16 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24120089
Special Instruction to ARC,if any	TP/GREAT AMERICAN
Prepared Date and Time	27/12/24 3:09 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,018.00	\$0.00
Total Spray Cost	\$1,794.00	\$0.00
Total Spare Part Cost	\$5,396.55	\$0.00
Total Other Cost	\$740.00	\$0.00
<b>TOTAL COST</b>	<b>\$8,948.55</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$8,950.00</b>	<b>\$0.00</b>
Number of Repair Days	6.0	
Prepared / Adjusted By	Mun San #	
ARC / Surveyor Sign Off Date		
Signature	SW	<input type="checkbox"/>
Remarks		

**Section C - Quotation and Accident Invoice Details**

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



to Consultants hence notify

the Repairer of the following: **SMRT Accident Vehicle Repair Estimates**

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

## Section D - Details of Repair Estimates

not Authorised  
for repair  
30/11/24  
P/P # 1260  
4 days

SMRT Automoto

60 Woodlands I

FAX Number :

Estimator Telep

Accident Repor

Date Generate

User ID

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$1,018.00	200
<b>Total Labour</b>	<b>\$1,018.00</b>	<b>500</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	200
TO RESPRAY REAR FENDER RH	\$378.00	200
TO RESPRAY REAR DOOR RH	\$378.00	200
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	11X
TO RESPRAY RIM	\$220.00	50
TO RESPRAY FILLER RR BUMPER RH	\$220.00	50
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,794.00</b>	

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	
TO TRANSFER DOOR MECHANISM	\$120.00	
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	
TO REPLACE SUNDRY PARTS	\$100.00	
<b>Total Other Costs</b>	<b>\$740.00</b>	

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Appr
		7585047910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$649.10	25.00	\$486.83	Replace	11X
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace	12X
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace	11X
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace	11X
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$4.30	25.00	\$6.45	Replace	11X
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace	11X
		5257547040	RETAINER, RR BUMPER, RH	1.00	\$127.40	25.00	\$95.55	Replace	11X
		5216116010	CLIPS PIECE, FRT BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	11X
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	11X
		5256547900	FILLER, RR BUMPER, RH	1.00	\$168.60	25.00	\$126.45	Replace	12X
		8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$489.00	25.00	\$366.75	Replace	11X
		8158147010	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$544.40	25.00	\$408.30	Replace	11X
		8149747020	COVER, REAR COMBINATION LAMP, RH	1.00	\$69.90	25.00	\$52.43	Replace	11X
		6700347210	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	13X



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automoto</b>
60 Woodlands I
FAX Number :
Estimator Telep
Accident Repor

Date Generate  
User ID

### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Appr
		6875020122	HINGE ASSY, REAR DOOR , UPPER RH	1.00	\$107.00	25.00	\$80.25	Replace	11X
		6877052031	HINGE ASSY, REAR DOOR , LOWER RH	1.00	\$93.90	25.00	\$70.43	Replace	11X
		6863047050	CHECK ASSY, REAR DOOR	1.00	\$199.40	25.00	\$149.55	Replace	11X
		6921147021A1	DOOR OUTER HANDLE REAR , RH	1.00	\$105.50	25.00	\$79.13	Replace	11X
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	25.00	\$707.33	Replace	RX
		6563747060	LINER, REAR FENDER , RH	1.00	\$151.10	25.00	\$113.32	Replace	11X
		4261147450	WHEEL, DISC	1.00	\$2,036.30	25.00	\$1,527.23	Replace	RX
		4245076020	HUB & BEARING ASSY WITH SPEED SENSOR , REAR AXLE , RH & LH	1.00	\$644.10	25.00	\$483.08	Replace	11X
			STICKER LOGO ( RR DOOR )	1.00	\$60.00	0.00	\$60.00	Replace	new ✓
Total					\$8,913.10		\$6,745.69		

### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Chec
Total									