

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ GA/ 24/ 20444/ Uv23**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: - SHD 6428Uat Workshop m/s SMCT

of _____

Insured: SKP 5495C

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

369k

Vehicle: IN / OUT

Date: _____ Person Contacted: LIA 7120Veh No: SHD 6428UYr Regn: 19/12/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Toyotac.c 1798Colour maroon

A/C: Insured / Std / NI / NA

Sp. Reading 760762

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB 3FU X0-3577003Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Green tracFront 6Rear 6

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. 6 mmL/Bal. 6 mmD.O.A. 27/12/24D.O.I. 30/12/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

21C Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

CRP until 18-12-2025

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: _____

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, \$ _____

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHD6428U
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8263848
Chassis No.:	JTDKB3FUX03577003
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,000.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$4,120.00
Total Rebate Amount:	\$7,120.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Dec 2024

OK

SMRT Accident Vehicle Repair Estimates

SMRT Auto
60 Woodlands I
FAX Number :
Estimator Telep
Accident Repor

Date Generate
User ID

TP
84

Great American

Section A - Accident Details	
Registration Number	SHD6428U
Case Reference Number	TAX/12/24/2092
Registration Date	19/12/17
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	SIM KWANG IMK
Type of Accident	Side Swipe
Accident Date and Time	27/12/24 9:20 AM
Accident Reported Date and Time	27/12/24 2:16 PM
Is Surveyor Required?	No
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24120089
Special Instruction to ARC,if any	TP/GREAT AMERICAN
Prepared Date and Time	27/12/24 3:09 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,018.00	\$0.00
Total Spray Cost	\$1,794.00	\$0.00
Total Spare Part Cost	\$5,396.55	\$0.00
Total Other Cost	\$740.00	\$0.00
TOTAL COST	\$8,948.55	\$0.00
Lump Sum Total	\$8,950.00	\$0.00
Number of Repair Days	6.0	
Prepared / Adjusted By	Mun San #	
ARC / Surveyor Sign Off Date		
Signature	8W	x
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

- To recover to original condition
- To display damaged parts
- To replace parts as required
- To carry out a "Warrant of Fitness" survey
- No legal modification(s) is allowed
- Supplementary item(s) must be added
- Estimate is subject to final approval from Insurer

Acknowledged by Reparer

Signature:

Section D - Details of Repair Estimates

NOT Affected
due
minor
30/11/24
P/P # 1260
4 days.

@ 1.40pm.

Zhe Jie Huang

SMRT Auto

60 Woodlands I

FAX Number :

Estimator Telep

Accident Repor

Date Generate

User ID

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$1,018.00	200
Total Labour	\$1,018.00	500

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	200
TO RESPRAY REAR FENDER RH	\$378.00	200
TO RESPRAY REAR DOOR RH	\$378.00	200
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	11 X
TO RESPRAY RIM	\$220.00	50
TO RESPRAY FILLER RR BUMPER RH	\$220.00	50
Total Spray Painting & Panel Beating	\$1,794.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	
TO TRANSFER DOOR MECHANISM	\$120.00	
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	
TO REPLACE SUNDRY PARTS	\$100.00	
Total Other Costs	\$740.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Appr
		7585047910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$649.10	25.00	\$486.83	Replace	11 X
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace	12 X
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace	11 X
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace	11 X
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$4.30	25.00	\$6.45	Replace	11 X
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace	11 X
		5257547040	RETAINER, RR BUMPER, RH	1.00	\$127.40	25.00	\$95.55	Replace	11 X
		5216116010	CLIPS PIECE, FRT BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	11 X
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	11 X
		5256547900	FILLER, RR BUMPER, RH	1.00	\$168.60	25.00	\$126.45	Replace	12 X
		8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$489.00	25.00	\$366.75	Replace	11 X
		8158147010	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$544.40	25.00	\$408.30	Replace	11 X
		8149747020	COVER, REAR COMBINATION LAMP, RH	1.00	\$69.90	25.00	\$52.43	Replace	11 X
		6700347210	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	11 X

SMRT Accident Vehicle Repair Estimates

SMRT Automot

60 Woodlands I

FAX Number :

Estimator Telep

Accident Repor

Date Generate

User ID

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Appr
		6875020122	HINGE ASSY, REAR DOOR , UPPER RH	1.00	\$107.00	25.00	\$80.25	Replace	11X
		6877052031	HINGE ASSY, REAR DOOR , LOWER RH	1.00	\$93.90	25.00	\$70.43	Replace	11X
		6863047050	CHECK ASSY, REAR DOOR	1.00	\$199.40	25.00	\$149.55	Replace	11X
		6921147021A1	DOOR OUTER HANDLE REAR , RH	1.00	\$105.50	25.00	\$79.13	Replace	11X
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	25.00	\$707.33	Replace	RX
		6563747060	LINER, REAR FENDER , RH	1.00	\$151.10	25.00	\$113.32	Replace	11X
		4261147450	WHEEL, DISC	1.00	\$2,036.30	25.00	\$1,527.23	Replace	RX
		4245076020	HUB & BEARING ASSY WITH SPEED SENSOR , REAR AXLE , RH & LH	1.00	\$644.10	25.00	\$483.08	Replace	11X
			STICKER LOGO (RR DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	new
Total					\$8,913.10		\$6,745.69		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Chec
Total									