



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: MARCUS XIAO

Ref: CS/INC24120445/Unh3e2(N)

Date: 16/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 7437Y	Veh. Inspected	SMH 6203X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1309948-001	Excess (\$)	0.00
Assign From	MARCUS XIAO	Assign Date	27/12/2024

2. Vehicle Particulars & Condition

Make & Model	MAZDA CX-3 2.0 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JM6DK2W7AK0416196	Colour	RED
Odometer	59641 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/50 R18	TOYO	7 mm
L/H Front Tyre	215/50 R18	TOYO	7 mm
R/H Rear Tyre	215/50 R18	TOYO	7 mm
L/H Rear Tyre	215/50 R18	TOYO	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/12/2024	Inspect Date / Time	07/01/2025 (10:31 AM)
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days