



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: SERENE			Ref: CS/FCI24120446/Uqp3m4(N) Date: 09/01/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3950Y	Veh. Inspected	SMW 855A
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D25000083MFCT	Excess (\$)	0.00
	Assign From	SWEE KEONG TEO	Assign Date	30/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT 1.3 (A)	c.c	1317
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	GR11002840	Colour	BLUE
	Odometer	139240 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60R15	TRIANGLE	6 mm
	L/H Front Tyre	185/60R15	TRIANGLE	6 mm
	R/H Rear Tyre	185/60R15	TRIANGLE	6 mm
	L/H Rear Tyre	185/60R15	TRIANGLE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/12/2024	Inspection Date	30/12/2024
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	