



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: ASTER QUEK

Ref: CS/INC24120447/Aqh3e2(N)

Date: 25/03/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMH 8444D	Veh. Inspected	SKX 8677M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1310033-002	Excess (\$)	0.00
Assign From	JULIET KOH	Assign Date	30/12/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ESTIMA	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	ACR507042511	Colour	WHITE
Odometer	298165 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	TOURADOR	6 mm
L/H Front Tyre	215/55 R17	TOURADOR	6 mm
R/H Rear Tyre	215/55 R17	TOURADOR	6 mm
L/H Rear Tyre	215/55 R17	TOURADOR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/12/2024	Inspect Date / Time	30/12/2024 (11:14 AM)
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**