

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24120449/UMA3Q2  
Date: 12/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002582\_01  
Claimant Vehicle No : SNR571H Insured Vehicle No : SLC6836H  
Date of Loss: 29/12/2024 Nature of Claim: TP Claim No: MFL2024D0015447

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNR571H  
Make & Model: HONDA STEPWAGON, 2.0 SPADA E:HEV (A) Engine No: LFA2241852  
Reg. Date: 24/05/2024 (Man. Year: 2024) Chassis No: RP81051847  
Colour: Black Odometer: 50998 km  
Engine Capacity: 1993 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm  
Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,504.28	4,572.52	6,931.76	60.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	1,580.00	2,740.00	63.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,824.28	6,152.52	9,671.76	61.12
Approved Total (Overridden) (S\$)		4,900.00		
Nett Amount (S\$)	15,824.28	4,900.00	10,924.28	69.03
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		5,247.25		
Global Sum Settlement (S\$)		5,240.00		

INSPECTION

Date of Assignment: 31/12/2024  
Date Inspected: 31/12/2024 Inspected At: Choo Motor Spray Painter (HQ)  
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit  
Singapore 417883  
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2025)
<b>Parts:</b>	M1-MPV	HONDA STEPWAGON 2.0 SPADA E:HEV (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNR571H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SLIDING DOOR N/S	Bent / Warped	2,855.20 FL	*2,605.10 FL
2	1		*REAR SLIDING DOOR INNER LOCK N/S	Serviceable	541.20 FL	*- FL
3	1		*ROCKER PANEL GARNISH N/S	Cut / Torn	399.20 FL	*399.20 FL
4	1		*REAR FENDER N/S	Repair	2,201.20 FL	*- FL
5	1		*REAR SPORT RIM N/S	Cut	960.00 FS	*600.00 FS
6	1		*REAR WHEEL HUB BEARING N/S	Damaged	645.80 FL	*645.80 FL
7	1		*REAR AXLE ARM ASSY	Not Necessary	2,842.20 FL	*- FL
8	1		*REAR ABSORBER N/S	Not Necessary	452.50 FL	*- FL
9	1		*REAR BUMPER	Cut / Torn	1,050.00 FL	*1,050.00 FL
10	1		*REAR BUMPER SIDE RETAINER N/S	Not Necessary	65.00 FL	*- FL
11	1		*REAR BUMPER LOWER CHROME MOULDING NS	Grazed	221.80 FL	*221.80 FL
12	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
13	1		*REAR FENDER GLASS SEALANT N/S	Not Necessary	40.00 FS	*- FS
14	1		*REAR SPORT RIM N/S	Repeated	1,200.00 FS	*- FS
15	1		*REAR TYRE N/S	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,759.10</b>	<b>5,556.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	2,254.82	984.38
<b>Total Parts (\$\$)</b>	<b>11,504.28</b>	<b>4,572.52</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY CERAMIC COATING	New	680.00	0.00
3	TO SPRAY RUST PROOFING	New	90.00	30.00
4	TO TRANSFER REAR SLIDING DOOR MECHANISM	New	120.00	50.00
5	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
6	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	New	280.00	120.00
7	TO RESET & DIAGNOSTIC SYSTEM	New	180.00	0.00
8	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	500.00
10	TO PUTTY & SPRAY PAINTING	New	1,480.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,320.00</b>	<b>1,580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >