


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 28.12.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLB6800R**
MODEL : **TOYOTA COROLLA ALTIS**
DATE OF ACCIDENT : 28.12.2024
TIME OF ACCIDENT : 11:30 HOURS

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Defend</i>	1	\$ 515.10	\$ 515.10
2	REAR BUMPER REFLECTOR <i>New</i>	2	\$ 68.10	\$ 136.20
3	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 120.10	\$ 240.20
4	REAR BUMPER REINFORCEMENT BRACKET LH <i>New</i>	1	\$ 90.10	\$ 90.10
5	REAR BUMPER REINFORCEMENT <i>Defend</i>	1	\$ 395.10	\$ 395.10
6	BOOTLID <i>Defend</i>	1	\$ 756.10	\$ 756.10
7	BOOTLID INSULATOR <i>New</i>	1	\$ 176.40	\$ 176.40
8	BOOTLID LAMP <i>New</i>	2	\$ 342.00	\$ 684.00
9	BOOTLID OUTER MOULDING (CHROME) <i>New</i>	1	\$ 426.00	\$ 426.00
10	BOOTLID DETECTOR <i>Defend</i>	1	\$ 385.00	\$ 385.00
11	BOOTLID LOGO	1	\$ 85.00	\$ 85.00
12	BOOTLID EMBLEM 'COROLLA' <i>New</i>	1	\$ 70.00	\$ 70.00
13	BOOTLID EMBLEM 'ALTIS'	1	\$ 70.00	\$ 70.00
14	BOOT LID HINGE <i>New</i>	2	\$ 70.00	\$ 140.00
15	BOOTLID TOP LOCK <i>Damaged</i>	1	\$ 318.10	\$ 318.10
16	BOOTLID LOWER LOCK <i>New</i>	1	\$ 20.00	\$ 20.00
17	BOOTLID STOPPER <i>New</i>	4	\$ 16.00	\$ 64.00
18	BOOTLID WEATHERSTRIP <i>at</i>	1	\$ 195.00	\$ 195.00
19	TAILLAMP <i>at</i>	2	\$ 465.00	\$ 930.00

✓
+
+
+
✓
-
+
+
+
195
✓
-
-
+
✓
+
+
✓

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLB6800R**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 28.12.2024
 TIME OF ACCIDENT : 11:30 HOURS

20	TAILLAMP LOWER BARCKET <i>new</i>	2	\$ 115.10	\$ 230.20	+
21	TAILLAMP LOWER PANEL LH <i>new</i>	1	\$ 253.40	\$ 253.40	+
22	REAR FENDER LH <i>Repair</i>	1	\$ 987.00	\$ 987.00	+
23	REAR FENDER INNER COWLING <i>2 new</i>	2	\$ 350.20	\$ 700.40	+
24	REAR FENDER INNER TRIM <i>AP LH torn</i>	2	\$ 770.10	\$ 1,540.20	+
25	REAR FENDER AIR VENT LH <i>new</i>	1	\$ 68.90	\$ 68.90	+
26	REAR WINDSCREEN <i>3 new</i>	1	\$ 1,328.10	\$ 1,328.10	+
27	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 163.00	\$ 163.00	+
28	REAR END PANEL <i>Dented</i>	1	\$ 695.30	\$ 695.30	-
29	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 250.10	\$ 250.10	✓
30	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$ 271.10	\$ 271.10	✓
31	REVERSE SENSOR <i>2 pieces damaged</i>	2	\$ 311.10	\$ 622.20	-
32	RESERVE CAMERA <i>new</i>	1	\$ 986.70	\$ 986.70	+
33	REVERSE SENSOR HOLDER <i>new</i>	2	\$ 69.30	\$ 138.60	100
34	REVERSE SENSOR WIREHARNES <i>new</i>	1	\$ 437.50	\$ 437.50	+
35	REAR CHASSIS MEMBER LH <i>Repair</i>	1	\$ 650.30	\$ 650.30	+

5863.10

4397.32

TOTAL PRICE \$ 15,019.30
 LESS 25% \$ 3,754.83
SUB TOTAL PRICE \$ 11,264.48

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20
3	BOOT LID INSULATOR CLIP (SET) <i>2 new</i>	1	\$ 80.00	\$ 80.00	+
4	TAILLAMP CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
5	TAILLAMP PANEL SEALANT <i>new</i>	1	\$ 120.00	\$ 60.00	+
6	REAR FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
8	REAR WINDSCREEN SEALANT <i>2 new</i>	1	\$ 80.00	\$ 80.00	+
9	REAR WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	+
10	REAR WINDSCREEN SOLAR FILM <i>new</i>	1	\$ 500.00	\$ 500.00	+
11	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLB6800R**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 28.12.2024
 TIME OF ACCIDENT : 11:30 HOURS

12	REAR END PANEL INSULATION SEAL <i>aler</i>	1	\$ 150.00	\$ 150.00
----	--	---	-----------	-----------

60

110

TOTAL \$ 1,270.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	<i>800</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>
8	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>X</i>
9	TRANFER BOOTLID MECHANISM	\$ 80.00	<i>60</i>
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>X</i>
11	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	<i>X</i>
12	VACCUM AND CLEAN FRONT WINDSCREEN GLASS SPLINTER	\$ 380.00	<i>X</i>

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLB6800R**
MODEL : **TOYOTA COROLLA ALTIS**
DATE OF ACCIDENT : 28.12.2024
TIME OF ACCIDENT : 11:30 HOURS

13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	x
----	--	-----------	---

1910

TOTAL \$ 5,550.00

TOTAL PARTS COST : \$ 12,534.48
TOTAL LABOUR COST : \$ 5,550.00
TOTAL REPAIR COST : \$ 18,084.48

Adrian King
2/s 30/12/24

06 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 6417.32
4/s: 51K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: