

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

not Authorized
me
30/12/24
1/5 \$ 7000
5 days

VEHICLE No: SNA 8639J

1PC	FRONT BUMPER	2099.82	Turn	\$2,850.00	—
1PC	FRONT BUMPER OUTER PROTECTOR N/S	266.00	Dis	\$355.00	—
1PC	FRONT BUMPER OUTER PROTECTOR MOULDING N/S		can	\$105.00	—
1PC	FRONT BUMPER FOG LAMP COVER N/S	152.00	Turn	\$188.00	—
1PC	FRONT BUMPER PDC SENSOR N/S		su	\$265.00	X
1PC	FRONT BUMPER BEAM		11	\$1,015.00	X
1PC	FRONT BUMPER SPONGE	160	Turn	\$248.00	—
1PC	FRONT BUMPER SIDE RETAINER N/S	90	one	\$108.00	—
1SET	FRONT BUMPER CLIPS & RIVET		111	\$60.00	—
1PC	HEADLAMP ASSY N/S	3805.00	holder cru	\$6,800.00	—
1PC	FRONT FENDER N/S		11	\$1,599.00	X
1PC	FRONT FENDER INNER SHIELD N/S	292	De/Torn	\$365.00	—
1SET	FRONT FENDER INNER SHIELD CLIPS N/S		111	\$60.00	—
1PC	FRONT FENDER OUTER PROTECTOR N/S	315	1102d	\$580.00	—
1PC	FRONT KNUCKLE ARM N/S		11	\$1,815.42	X
1PC	FRONT KNUCKLE ARM BEARING N/S		11	\$680.00	X
1PC	FRONT LOWER ARM N/S		11	\$845.00	X
1PC	WASHER TANK		de	\$292.00	—
1PC	FRONT SUPPORT CARRIER	740.00	111	\$1,450.00	—
				\$19,680.42	
				LESS 10%	\$17,712.38

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX FRONT PDC SENSOR	\$80.00	30
TO SPRAY RUST PROOFING	11	\$100.00 X
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	11	\$280.00 X
TO CONDUCT WHHEL ALIGNMENT	11	\$150.00 X
TO RESET & REPROGRAMME SYSTEM		\$100.00 50
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$800.00 680
TO PUTTY & SPRAY PAINTING		\$800.00 400
TOTAL		\$20,072.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 8476.82
102
7629.14
1120
8809.14
7047