



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 3347H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR RH DOOR	TO REPAIR SEE LABOUR	1,514.00	-
1	REAR RH FENDER	TO REPAIR SEE LABOUR	1,025.00	-
1	RH SIDE MIRROR	NOT NECESSARY	500.00	-
	LESS 20% DISCOUNT		-607.80	-
			2,431.20	-
<u>SPECIAL NETT ITEMS</u>				
1	REAR FENDER QUARTER GLASS SEALANT RH (SN)	NOT NECESSARY	80.00	-
1	ROCKER PANEL SEALANT RH (SN)	NOT NECESSARY	60.00	-
			140.00	-
<u>LABOUR</u>				
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
	SPRAY PAINT ON AFFECTED AREAS.		800.00	450.00
	PANEL BEAT ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR RH DOOR AND REAR RH FENDER.		400.00	200.00
	ALIGNMENT.		80.00	80.00
			1,430.00	730.00
GRAND TOTAL			4,001.20	730.00
RECOMMENDED COST OF REPAIRS				730.00

Report Ref No. CS/AGI24120455/Eqp3e2(N)

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.